NAVFAC MIDLANT, FEAD Beaufort [mailto: (b) (6) @navy.mil] Sent: Thursday, April 20, 2017 7:51 AM CTV NAVFAC MIDLANT, FEAD Beaufort NAVFAC MIDLANT, FEAD CIV MARFORCOM; FEAD Beaufort; Beaufort Subject: RE: weekly meeting I am cancelling today's meeting to allow for maximum participation by your staff. V/R MCAS Beaufort @carothersconstruction.com] From: (b) (6) Sent: Wednesday, April 19, 2017 1:01 PM NAVFAC MIDLANT, FEAD Beaufort Subject: [Non-DoD Source] weekly meeting



From: Sent:

To:

Subject: Signed By: (b) (6)

NAVFAC MIDLANT, FEAD Beaufort

Thursday September 21, 2017 11:19

(b) (6)

@carothersconstruction.com);

b) (6)

@carothersconstruction.com)

Pre-Warranty Conference

(b) (6)

@navy.mil



Below is the guidance for the pre-warranty conference. Let me know if you have any questions.

Develop a warranty management plan for this project. Include within the warranty management plan all required actions and documents to assure that the Government receives all warranties to which it is entitled. The plan must be in narrative form and contain sufficient detail to render it suitable for use by future maintenance and repair personnel, whether tradesmen, or of engineering background, not necessarily familiar with this contract. Include within the warranty management plan, but not limited to, the following:

- 1. Roles and responsibilities of all personnel associated with the warranty process, including points of contact and telephone number within the organizations of the Contractors, subcontractors, manufacturers or suppliers involved.
- 2. Furnish with each warranty the name, address, and telephone number of each of the guarantor's representatives nearest to the project location.
- 3. Listing and status of delivery of all Certificates of Warranty for extended warranty items, to include roofs, HVAC balancing, pumps, motors, transformers, and for all commissioned systems such as fire protection and alarm systems, sprinkler systems, lightning protection systems, etc.
- 4. A list for reach warranted equipment, item, feature of construction or system indicating:
- a. Name of item
- b. Model and serial numbers.
- c. Location where installed.
- d. Name and phone numbers of manufacturers or suppliers.
- e. Names, addresses and telephone numbers of sources of spare parts.
- f. Warranties and terms of warranty. Include one-year overall warranty of construction, including the starting date of warranty of construction. Items which have extended warranties must be indicated with separate warranty expiration dates.
- g. Cross-reference to warranty certificates as applicable.
- h. Starting point and duration of warranty period.
- i. Summary of maintenance procedures required to continue the warranty in force.
- j. Cross-reference t specific pertinent Operation and Maintenance manuals.
- k. Organization, names and phone numbers of persons to call for warranty service.
- I. Typical response time and repair time expected for various warranted equipment.
- 5. Furnish the name, telephone number and address of a license and bonded company which is authorized to initiate and pursue construction warranty work action on behalf of the Contractor.


V/R



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 95 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 3/30/2017





Fax: (662) 234-3292

# Carothers/NAVFAC Weekly Meeting #95

**Project:** 

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

March 30, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

# Agenda:

# I. Safety(b) (6)

- a) 228 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Five Hundred Sixty-Three (563) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Four (4), no new items
  - Deficiency Log updated 03/29/2017
- f) Deficiency Log
  - A total of Two Hundred Thirty-Four (242) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:
- h) AHA/Activities about to start:
  - DeWeese AFFF Began (03/27/2017 Shoring, DeWatering)
  - Preferred Materials Asphalt
  - Seed Slingers AHA's approved 03/29/2017
- i) Weekly Safety Meeting Topic
  - PPE
  - Red Taped (Danger) Areas
  - Clean up/Trash
  - Parking Lot Grading Work



Fax: (662) 234-3292

# II. Quality Control (b) (6)

a) Re-Work Log.

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

# c) Upcoming Preparatory Meetings:

- Flexible Lifeline Fall protection system
- Sodding
- Landscape Establishment
- Exterior Plants

# d) Upcoming Initial Meetings:

- Translucent Panels
- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed, will schedule once initial tests are completed and before devices are installed. -TBD
- Sump Pumps
- 400 Hz converter
- Bituminous tack and prime coat and hot mix asphalt Scheduled for 4/3/17

# e) General Quality Control Items:

- NAVFAC- please ask ATSI/MCAS, whoever their contract is with, to request that BJWSA and SCE&G update as-builts in my office or provide to NAVFAC, and we will incorporate them into our As-Built packages. Will also need chlorination reports from BJWSA. -Outstanding
  - BJWSA Responded regarding As-Builts, but SCEG has not. Still have not received from either company
- Terracon-Scheduled to witness bedding and backfill for AFFF tank. Also scheduled for densities of parking lot prior to asphalt paving
- Awaiting response from STOA regarding close proximity of ACCU to water line –
   Response received from mechanical DOR and civil DOR. "There is not a code requirement for separation distance between air piping and water piping" No issues noted with installation
- 1<sup>st</sup> Floor Above Ceiling conducted on Friday, March 24, 2017 at 10 AM. Punch list has been generated and distributed to subs. Will re-inspect once all items have been corrected.
- Awaiting startup procedures, checklists, etc from HVAC contractor for mechanical and plumbing equipment. Update: Startup procedures, checklists received but additional information is needed from manufacturer's.
- Firestopping final inspection performed by 3M manufacturer's representative. Final report to follow
- Duct installation Discrepancy in exposed ceiling areas

### **SAPF Issues**

- Ongoing photo documentation of SAPF construction.
- Coordination taking place for north wall in Room #232 security office (b) (6) coordinating with (b) (6) Will schedule inspection with NAVFAC once rough in is complete



Fax: (662) 234-3292

# Area B:

• Drywall boxes under electrical floor boxes not built yet.

### Ready Room:

No issues other than level finish above ceiling

III. RFIs(b) (6)

- a) Outstanding RFIs Government
  - RFI #121 AA storm line conflict
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - None
- d) Outstanding RFVs
  - None

# IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

# Submitted Awaiting Approval:

- PC-037- 400 Hz Changes- Awaiting official modification (zero cost). Verbal Approval no Mod. Issued
- PC-042- Triple Coat Epoxy Flooring for shop rooms in Admin. Preliminary Approval no Mod. from Gov. Issued.
- PC-035 Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC.

### In Development:

NONE

# Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Sweeping at regular intervals throughout each work day.

# Outstanding Schedule Items:

Schedule Days submitted to Navy		
Badging Delays	77	Calendar Days
Days owed from original Hurricane Claim	7	Calendar Days
Days submitted for Cooling Pit Repairs	26	Calendar Days
PC - 042 Triple Vs. Single Coat Epoxy Flooring	15	Calendar Days
AHA Delay for Sheet Piling and Well Point System	22	Calendar Days
Total	147	Calendar Days



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

V. Schedule (b) (6)

See Attached Schedule

# Administrative (b) (6)

- AA storm drain line
- Turnstile and associated equipment
- Redzone Meeting Monday 4/3/17
- Coordination with Bldg 1039 regarding closing of access
- Air Show work Schedule
- Parking for Paving next week



Fax: (662) 234-3292

# Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Report Type: Open Items

Re-Work Log

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Project:

Date: 3/30/2017 Total Items: 17

Days Open Calculated by: Calendar Days since date Initially Created

105	103	102	101	93	90	89	87	82	75	Item #
South elevation Hangar- east/west end	floor second floor railing .	Painted gyp board walls throughout admin - 1st and 2nd	2nd floor elevator threshold	Room Railing	Room 131 Water	Structure 11D	Cable Tray Chiller Location	First Floor Corridor	East Elec Room#111	Location BOX CULVERT
caged ladders missing bolts at feet and vertical legs	railing bent	Intermediate coat of paint applied without wall touch up being performed	roof color.  Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	attached this color is safety yellow and on IFC plans, it is to match the	Tanks damaged see photos	debits may be the cause for this Storm Pipe not cut flush with structure and parged	need to be removed from cable tray Hurricane Mathew- Chiller damaged by Storm- flying	applying paint to steel Overspray from painters will	No Surface prep before	<u>Description</u> Cracked Mortar
									(0)	Created By
									(0)	Responsible Party
03/31/2017	04/17/2017	04/28/2017	03/31/2017	02/24/2017	01/31/2017	12/16/2016	11/22/2016	09/16/2016	08/09/2016	Due Date 11/06/2015
New	New	New	New	New	New	New	New	New	New	Status Fix Not Accepted
corrected	(b) (6) will notify QC dept once		Date entered is date found / damaged	date entered is date found	NAVFAC.  Date entered is date found	QCM will inpsect all manholes upon closeout and completion of this FOW. FOW is work in progress. Date entered is date found by		date entered is date found	remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.  Date entered is date found	Comments  Work has been completed,QC inspections were held and deficient areas were
22	23	29	63	105	106	112	163	205	247	Days Open 524

Project: Report Type: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Open Items Days Open Calculated by: Calendar Days since date Initially Created Date: 3/30/2017 Total Items: 17

Re-Work Log

	112	=	110	108	107	Item #
throughout 2nd floor	#208 Various room	admin area CO Waiting Room	Bay 4  Various exterior  windows throughout	parking garage Hangar Bay 1 and	limits Fire Lane drive between admin and	Location On site within project
not set correctly and are creating small gaps at edges of ceiling grid	thread bent and skewed HVAC grills in ceiling grid are	Electrical junction box all	Patric doors Weather stripping and sill caps not installed correctly	of concrete per IFC docs Tear in fabric on vertical lift	work under FEAD/NAVFAC core holes to determine consolidation and overall depth	<u>Description</u> Red Lines-As-Builts for all
				\ \	(D)	Created By
				_		Responsible Party
	04/19/2017	03/24/2017	03/31/2017	04/28/2017	11/07/2016	Due Date 03/31/2017
	New	New	New	New	New	Status
				Replacement fabric ordered. eta to site 28 March.	superintendent (b) (6) will be responsible for correcting this is sue	Comments previoutsy asked both NAVFAC/SCE&G/and B IM/SA with no response or action taken
	s	14	74	16	22	Days Open 22

CONSTRUCTION, INC.

Report Type:

Project:

G Submittal

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Days Open Calculated by: Calendar Days since date Initially Created Total Items: 3

Date: 3/30/2017

		-		
Government Safety Requirements for Design-Build	Documentation For Design-Build	Design-Build 013329.0525 LEED(TM)	013329.0525 LEED(TM) Documentation For	Section
	013526.0525-	013329.0525-	013329.0525- 3	Item#
Crane for Crane System Installation 03-25-2017 Resubmittal of Submittal #501 AHA for Cincinnati Crane for Installation of Crane 07-15-2016	Resybmittal #501.2 AHA for Cincinnati	013329.0525- Transmittal #649 LEED Implementation Plan	013329.0525- Transmittal #643 Leed Checklist 3	Description
Crane	Cincinatti	Carothers Construction	Carothers Construction	Supplier or Manufacturer
	03/23/2017	03/27/2017	03/16/2017	Date from Sub
	03/25/2017	03/29/2017	03/27/2017	Date from Carothers
				Review by
				Review by Arch
				Return to Sub
				Action
	Cons	Cons	Cons	B-I-C
	7	ω	14	<u>Days</u> <u>Open</u>



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 96 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 4/6/2017

Name:	Organization/Company Name:	Phone Number:	Email	:	
o) (6)	Carothers Construction NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC			(6	



Fax: (662) 234-3292

# Carothers/NAVFAC Weekly Meeting #96

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

April 6, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

# Agenda:

# I. Safety (b) (6)

- a) 235 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Five Hundred Sixty-Seven (567) total site safety orientations have been completed to date.
- c) Accidents to Date
  - new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Four (4), no new items
  - Deficiency Log updated 04/05/2017
- f) Deficiency Log
  - A total of Two Hundred Forty-Six (246) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:
- h) AHA/Activities about to start:
  - DeWeese AFFF Began (03/27/2017 Shoring, Dewatering)
  - Preferred Materials Asphalt (Due to weather 04/07/2017 Start)
  - Seed Slingers AHA's (Stopped work due to weather conditions)
- i) Weekly Safety Meeting Topic
  - PPE
  - Electrical Rooms Access
  - Damage to Finished work
  - Trash/Clean Up
  - Parking/Site Changes



Fax: (662) 234-3292

# II. Quality Control (b) (6)

# a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

# c) Upcoming Preparatory Meetings:

Bridge Crane

# d) Upcoming Initial Meetings:

- Translucent Panels
- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed, will schedule once initial tests are completed and before devices are installed. -TBD
- Sump Pumps
- 400 Hz converter
- Bituminous tack and prime coat and hot mix asphalt Scheduled for 4/7/17

# e) General Quality Control Items:

- NAVFAC- please ask ATSI/MCAS, whoever their contract is with, to request that BJWSA and SCE&G update as-builts in my office or provide to NAVFAC, and we will incorporate them into our As-Built packages. Will also need chlorination reports from BJWSA. -Outstanding
  - BJWSA Responded regarding As-Builts, but SCEG has not. Still have not received from either company
- Terracon-Witnessed bedding and backfill for AFFF tank. Also scheduled for densities of parking lot prior to asphalt paving
- Awaiting startup procedures, checklists, etc from HVAC contractor for mechanical and plumbing equipment. Update: Startup procedures, checklists received but additional information is needed from manufacturers.
- Waiting on revised commissioning plan from commissioning agent
- Firestopping final inspection performed by 3M manufacturer's representative. Final report to follow
- Duct installation Discrepancy in exposed ceiling areas; DOR working on revised specs
- Sidewalk and curb and gutter deficiencies
- AFFF tank set in place American made turnbuckles arrive on site today to replace the Chinese made turnbuckles sent with tank. Installation will be per manufacturer's instruction booklet
- Awaiting completed punch lists for 1<sup>st</sup> floor above ceiling inspection
- Ceiling height changes approved by (b) (6) in rooms 117, 212, and 143. Ceilings to be lowered 2"



Fax: (662) 234-3292

### **SAPF Issues**

- Ongoing photo documentation of SAPF construction.
- Coordination taking place for north wall in Room #232 security office Randy coordinating with Pete Robson. Will schedule inspection with NAVFAC once rough in is complete

## Area B:

• Drywall boxes under electrical floor boxes not built yet.

# Ready Room:

No issues

# III. <u>RFIs</u>(b) (6)

- a) Outstanding RFIs Government
  - None
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #229 Landscape conflict at south side of parking garage
  - RFI #230 Landscape conflict at NW side of parking lot
  - RFI #231 Landscape conflict adjacent to box culvert
- d) Outstanding RFVs
  - None



Fax: (662) 234-3292

# IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

# Submitted Awaiting Approval:

- PC-037- 400 Hz Changes- Awaiting official modification (zero cost). Verbal Approval no Mod.
- PC-042- Triple Coat Epoxy Flooring for shop rooms in Admin. Preliminary Approval no Mod. from Gov. Issued.
- PC-035 Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC.

### In Development:

NONE

# Storm-water/Erosion Controls-


- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Sweeping at regular intervals throughout each work day both around project perimeter and at construction entrance
  - Silt bags have some sediment in them and will be cleaned next opportunity. However they are preventing the sediment from entering the waters downstream
  - Concrete Washout is working properly will be cleaned at next opportunity
  - Construction entrance has been removed to facilitate asphalt placement which was schedule for Tuesday this week and has been pushed back due to inclement weather conditions.



See Attached Schedule

# Administrative (b) (6)

- · AA storm drain line
- Turnstile and associated equipment
- Redzone Meeting Monday 2 May 2017
- Coordination with Bldg 1039 regarding closing of access
- · Air Show work Schedule



Log:

Re-Work Log

Project:

35

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

CONSTRUCTION, INC.
Our Expression of Burneling Series 1987

Date: 4/6/2017 Total Items: 16

Days Open Calculated by: Calendar Days since date Initially Created

Item# BOX CULVERT Location Chiller Location Structure 11D First Floor Corridor East Elec Room#111 Hangar- east/west South elevation second floor railing admin - 1st and 2nd walls throughout Painted gyp board threshold 2nd floor elevator Railing Roof Hatch Safety Room Room 131 Water Cable Tray No Surface prep before Cracked Mortar need to be removed from Overspray from painters will caged ladders missing bolts at being performed applied without wall touch up and will need to be replaced. Fire Rated Expansion Joint on IFC plans, it is to match the this color is safety yellow and attached structure and parged Storm Pipe not cut flush with debris may be the cause for damaged by Storm- flying Hurricane Mathew- Chiller cable tray applying paint to steel railing bent Intermediate coat of paint Material flashing is damaged roof color. Tanks damaged see photos Description Due Date 08/09/2016 11/06/2015 03/31/2017 01/31/2017 09/16/2016 04/28/2017 02/24/2017 11/22/2016 03/31/2017 04/17/2017 12/16/2016 New New New New New New New Fix Not Accepted Status New New New Work has been completed,QC inspections Date entered is date found questioning entire installation...no change in of correction, NAVFAC QA is now remediated, pictures were provided as proof Date entered is date found / damaged and completion of this FOW. FOW is work in date entered is date found this issue for several months were held and deficient areas were Comments corrected date entered is date found Date entered is date found NAVFAC. progress. Date entered is date found by QCM will inpsect all manholes upon closeout will notify QC dept once Days Open 531 212 254 119 170 113 112 30 36 70 29

103

105

feet and vertical legs

102

101

93

90

89

87

82

75

Date: 4/6/2017

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Re-Work Log

Open Items

Report Type: Project:

Total Items: 16

Days Open Calculated by: Calendar Days since date Initially Created

		112		111			110			107		106	Ite
	throughout 2nd floor	2 Various room	#208	1 CO Waiting Room	admin area	windows throughout	0 Various exterior	parking garage	between admin and	7 Fire Lane drive	limits	6 On site within project	Item# Location
creating small gaps at edges	not set correctly and are	HVAC grills in ceiling grid are	thread bent and skewed	Electrical junction box all		not installed correctly	Weather stripping and sill caps	of concrete per IFC docs	consolidation and overall depth	core holes to determine	work under FEAD/NAVFAC	Red Lines-As-Builts for all	Description
													Created By
													Responsible Party
		04/19/2017		03/24/201/			03/31/2017	2000		11/0//2016		03/31/2017	Due Date
		New		New			New			New		New	Status
									responsible for correcting this issue	superintendent	DITSE OF AC	previoulsy asked both NAVEAC/SCE&G/and	Comments
			10		21			21			29		Days Open

of ceiling grid



Report Type:

All Items

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

G Submittal

Project: Log:

Days Open Calculated by: Calendar Days since date Initially Created

Date: 4/6/2017 Total Items: 2

013329.0525 LEED(TM) Documentation For	Documentation For Design-Build	LEED(TM)	013329 0525	Section	
013329.0525-		3	013329.0525-	Item#	
013329.0525- Transmittal #049 LEED Implementation Flant 4	Total Para Tara Tara Tara Tara Tara Tara Tara		013329,0525- Transmittal #643 Leed Checklist	Description	
Construction	Carothers	Construction	Carothers	Manufacturer	Supplier or
00000	03/27/2017		03/16/2017	Sub	Date from
	03/29/2017		03/27/2017	Carothers	Date from
				Cons	Review by
				Arch	Review by
				Sub	Return to
				Action	
	Cons		Cons	B-1-C	
	10		21	Open	Days

Design-Build



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 97 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 4/13/2017

Name:	Organization/Company Name:	Phone Number:	Eı	mail:	
(b) (6)	Carothers Construction NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC				



Fax: (662) 234-3292

# Carothers/NAVFAC Weekly Meeting #97

Project:

P465 Aircraft Hangar

**Contract:** 

N69450-14-D-1266

Date:

April 13, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

# Agenda:

# I. Safety(b)(6)

a) 242 Days worked with Two (2) recordable incidents.

# b) Site Safety Orientations to Date:

• Five Hundred Sixty-Seven (576) total site safety orientations have been completed to date.

# c) Accidents to Date

• 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.

# d) First Aids to Date

• 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.

# e) Near Misses to Date

- Four (5), 04/06/2017 DeWeese Tank rolled over and almost hit a worker while he was in the hole working on de-watering of the hole.(Submitted to NAVFAC on 04/07/2017 Lane Anderson)
- Deficiency Log updated 04/12/2017

# f) Deficiency Log

- A total of Two Hundred Fifty-One (251) deficiencies have been logged for the project.
- No Tolerance Project began 07/19/2016

# g) AHA/Activities Reviewed:

Transmittal #655 AHA for DeWeese Construction (Crane/AFFF Installation)

# h) AHA/Activities about to start:

- Preferred Materials Asphalt (Began on 04/10/2017)
- Seed Slingers AHAs (Began work on 04/10/2017)

# i) Weekly Safety Meeting Topic

- PPE
- Electrical Rooms/Panels
- Site Clean Up
- Parking/Site Conditions



Fax: (662) 234-3292

# II. Quality Control (b) (6)

a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

# c) Upcoming Preparatory Meetings:

None

# d) Upcoming Initial Meetings:

- Translucent Panels-Scheduled for 4/14/17
- Bridge Crane
- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed, will schedule once initial tests are completed and before devices are installed. -TBD
- Sump Pumps
- 400 Hz converter

# e) General Quality Control Items:

- NAVFAC- please ask ATSI/MCAS, whoever their contract is with, to request that BJWSA and SCE&G update as-builts in my office or provide to NAVFAC, and we will incorporate them into our As-Built packages. Will also need chlorination reports from BJWSA. -Outstanding
  - BJWSA Responded regarding As-Builts, but SCEG has not. Still have not received from either company
- Terracon-Densities taken of parking lot prior to asphalt paving; Will be scheduled to witness bedding installation and recommendations for AFFF tank once it is ready to be reinstalled
- Awaiting startup procedures, checklists, etc from HVAC contractor for mechanical and plumbing equipment. Update: Startup procedures, checklists received but additional information is needed from manufacturers.
- Revised commissioning plan submitted. Pre-Commissioning meeting scheduled for Wednesday, April 19th
- Duct installation Discrepancy in exposed ceiling areas; DOR sent letter regarding installation
- AFFF tank Information sent to DOR for revised drawings and elevations for tank
  installation based on manufacturer's recommendations. Installation will be per
  manufacturer's instruction booklet. Tank to be removed from hole and re-certified once the
  revised crane plan is approved. Deweese received Xerxes installation certification
  yesterday
- Awaiting completed punch lists for 1<sup>st</sup> floor above ceiling inspection-Still outstanding
- Walk through with Joe Otterbine conducted yesterday to review bracing and sprinkler installation issues with subcontractor as noted during overhead inspections. Work will be completed and re-inspected
- Air compressor reel locations Letter received from STOA/ICT regarding locations
- Accent wall paint colors S Roberts to confirm intent on Drawings I-106-I-109
- Coordination taking place with crane subcontractor and electrical and hvac subs for work in hangar



Fax: (662) 234-3292

### **SAPF** Issues

- Ongoing photo documentation of SAPF construction.
- Coordination taking place for north wall in Room #232 security office Will schedule inspection with NAVFAC once rough in is complete

### Area B:

• Drywall boxes under electrical floor boxes not built yet.

## Ready Room:

No issues

# III. RFIs(b) (6)

- a) Outstanding RFIs Government
  - None
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #229 Landscape conflict at south side of parking garage
  - RFI #230 Landscape conflict at NW side of parking lot
  - RFI #231 Landscape conflict adjacent to box culvert
- d) Outstanding RFVs
  - None

### IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

### Submitted Awaiting Approval:

 PC-035 – Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC.

### In Development:

NONE

# Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Sweeping at regular intervals throughout each work day both around project perimeter and at construction entrance
  - Silt bags have some sediment in them and will be cleaned next opportunity. However they are preventing the sediment from entering the waters downstream
  - Concrete Washout is working properly will be cleaned at next opportunity
  - Construction entrance has been removed to facilitate asphalt placement which was schedule for Tuesday this week and has been pushed back due to inclement weather conditions.



Fax: (662) 234-3292

See Attached Schedule

# Administrative (b) (6)

- · AA storm drain line
- Turnstile and associated equipment
- Redzone Meeting 5/6/17
- Coordination with Bldg 1039 regarding closing of access
- Air Show work Schedule

# Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.

ORACLE Primavera Submittal Ex

Project: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Project Number: 513

Submittal CONSTRUCTION INC

View: My Activity | All Activity

Div: 01

Government Safety 013526.0525 Requirements for Design-Build Section Number Section Title 013526.0525-317

Submittal # Classification Description Charles DeWeese Cons... Supplier or Manufacturer Expected Date

Submittal #655 AFFF ...

4/12/17

4/12/17 4/12/17 2 11 4/12/17

Date Type Sent to Date Type Sent to Reviewed Type Action

Returned to Type Action Carothers

4/19/17

Requested

Date

Submittal from Subcontractor

from Carothers

Review by Consultant

Review by Architect

Returned to Sub

Remarks

https://www.submittalexchange.com/ProjectLog.aspx?p=9ACAA37ADF&log=145857



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 98 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 4/27/2017

Name:	Organization/Company Name:	Phone Number:	Email:	
b) (6)	Carothers Construction NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC			



Fax: (662) 234-3292

# Carothers/NAVFAC Weekly Meeting #98

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

April 27, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

# Agenda:

# I. <u>Safety</u> (b) (6)

- a) 249 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Five Hundred Seventy-Eight (578) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Four (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 04/26/2017
- f) Deficiency Log
  - A total of Two Hundred Fifty-One (251) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:

N/A

# h) AHA/Activities about to start:

• DeWeese – AFFF Tank Re-installation 05/01/2017

# i) Weekly Safety Meeting Topic

- PPE
- Electrical Rooms/Panels
- Site Clean Up
- Air Show Prep
- Equipment



Fax: (662) 234-3292

# II. Quality Control (b) (6)

a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G Submittal" Tab:</u>

See Attached

# c) Upcoming Preparatory Meetings:

None

# d) **Upcoming Initial Meetings:**

- Bridge Crane-Will be scheduled once date that crane installer will be on site is confirmed
- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed, will schedule once initial tests are completed and before devices are installed. -.
   TBD
- Sump Pumps
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed
- Solid Surface
- Finish carpentry

# e) General Quality Control Items:

- NAVFAC- please ask ATSI/MCAS, whoever their contract is with, to request that BJWSA and SCE&G update as-builts in my office or provide to NAVFAC, and we will incorporate them into our As-Built packages. <u>BJWSA Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either company
- Terracon-Scheduled to witness bedding installation and recommendations for AFFF tank on Monday, May 1
- Startup procedures, checklists, etc from HVAC contractor for mechanical and plumbing equipment received and submitted. Discussing submittal requirements with DOR for items that are included in commissioning
- Revised commissioning plan will be resubmitted today. AHU startup to take place Tuesday, May 2nd
- Duct installation Discrepancy in exposed ceiling areas; DOR sent letter regarding installation. Randy to send in CO
- AFFF tank Information sent to DOR for revised drawings and elevations for tank
  installation based on manufacturer's recommendations. Installation will be per
  manufacturer's instruction booklet. Tank removed from hole and awaiting recertification
  from manufacturer. Revised submittal submitted and awaiting government approval
- Sprinkler installation issues with subcontractor were noted during overhead inspections.
   Work will be completed and re-inspected. Update: Awaiting sprinkler sub on site to finish work
- Accent wall paint colors (b) (6) to confirm intent on Drawings I-106-I-109. Awaiting revised drawings from STOA
- Coordination taking place with crane subcontractor and electrical and HVAC subs for work in hangar. Revised drawings forthcoming from crane sub for submittal



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

 SF-6 switch testing not complete. Will schedule once loop is complete and new wire pulled and in place. Will coordinate outage with NAVFAC once a date is provided for outage by subcontractor. Control curves and information on surge arrestors will be sent to NAVFAC this week.

• Walk through conducted on 2<sup>nd</sup> floor restrooms with ceramic tile. Deficiencies noted and being reworked.

- QC tests to be scheduled with Preferred Materials and third party testing agency for May 2<sup>nd</sup>. Will send Outlook invite once a time is received and confirmed.
- Solar water heating pressure test to be conducted next week. Awaiting calibrated gauge.
   Will schedule with NAVFAC once a specific date and time is determined.
- Hangar light installation coordination taking place
- AFFF tank installation coordination taking place with DOR based on NAVFAC comments and response to MOD 06. Information will be sent to NAVFAC once it is received from DOR.
- Awaiting gas piping FACTORY test results per API Std 598 and API Std 607 from manufacturer. Will send once received.
- Parking garage walk through and turnover
- Coordination meeting requested on 04/26/17 with base communications office. Awaiting response.

# **SAPF Issues**

- Ongoing photo documentation of SAPF construction.
- Coordination taking place for north wall in Room #232 security office Will schedule inspection with NAVFAC once rough in is complete. Wall is complete except for rough in for two-way speaker. Coordination taking place with Pete Robson on requirements.
- Holes made after overhead inspection to be sealed
- Sprinkler piping bracing to be installed per plans

### Area B:

None

### Ready Room:

No issues

# III. RFIs (b) (6)

- a) Outstanding RFIs Government
  - RFI #122 Landscape change at south side of parking garage
  - RFI #123 Landscape change at NW side of parking lot
  - RFI #124 Landscape change adjacent to box culvert
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
- d) Outstanding RFVs
  - None



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

# Submitted Awaiting Approval:

 PC-035 – Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC.

# In Development:

NONE

# Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - All systems inspected this week and are functioning properly
  - Concrete washout pit to be reworked after AFFF tank is installed

# V. Schedule (b) (6)

See Attached Schedule

# Administrative (b) (6)

- AA storm drain line (start work 7 May)
- Turnstile and associated equipment
- Redzone Meeting 5/2/17
- Coordination with Bldg 1039 regarding PMO decision about fence
- · Air Show preparation
- Sat/Sun refueling
- O & M training
- Deleted Eye Wash in Room #127
- Coordination Meeting regarding placement of boxes in rooms #230 & 232



Fax: (662) 234-3292

# Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Report Type: Open Items

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Re-Work Log

Project:

Total Items: 17

Date:

4/27/2017

Days Open Calculated by: Calendar Days since date Initially Created

			_	~	~	(0)	93	_	-	=	=	=
item #	35	75	82	87	89	90	ŭ.	101	103	105	106	110
Location	BOX CULVERT	East Elec Room#1111	First Floor Corridor Cable Tray	Chiller Location	Structure 11D	Room 131 Water Room	Roof Hatch Safety Railing	2nd floor elevator threshold	second floor railing . South elevation	Hangar- east/west end	On site within project limits	Various exterior windows throughout
Description	Cracked Mortar	No Surface prep before applying paint to steel	Overspray from painters will need to be removed from cable tray	Hurricane Mathew- Chiller damaged by Storm- flying debris may be the cause for this	Storm Pipe not cut flush with structure and parged	Tanks damaged see photos attached	this color is safety yellow and on IFC plans, it is to match the roof color.	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	railing bent	caged ladders missing bolts at feet and vertical legs	Red Lines-As-Builts for all work under FEAD/NAVFAC	Weather stripping and sill
Created By	(d)											
Responsible Party	(6)											
<b>Due Date</b>	11/06/2015	08/09/2016	09/16/2016	11/22/2016	12/16/2016	01/31/2017	02/24/2017	03/31/2017	04/17/2017	03/31/2017	03/31/2017	03/31/2017
Status	Fix Not Accepted	New	New	New	New	New	New	New	New	New	New	New
Comments	Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.	Date entered is date found	date entered is date found		QCM will inpsect all manholes upon doseout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.	Date entered is date found	date entered is date found	Date entered is date found / damaged	(b) (6) will notify QC dept once		previoulsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.	
Days Open	562	275	233	191	140	134	133	91	51	50	50	42

Re-Work Log



Project: Report Type: Open Items Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Date: Total Items: 17 4/27/2017

Days Open Calculated by: Calendar Days since date Initially Created

116	=	=	-	_	=	
	115	114	113	112	Item#	
Room 106 top of walls	Various locations - Communication rooms	East side of parking garage	Parking Lot	Various room throughout 2nd floor	Location	
Gypsum board wall supports on south wall exposed	Fire rated comm backboard not UL labeled	Light pole base on east side of parking garage not level	Handicap sidewalks do not meet ADA requirements	HVAC grilts in celling grid are not set correctly and are creating small gaps at edges of cailing grid	Description	
					Created By	
				6	Responsible Party	
05/31/2017	05/31/2017	05/19/2017	04/21/2017	04/19/2017	Due Date	
New	New	New	New	New	Status	
					Comments	
00	ω	14	21	31	Days Open	



# Report Type: All Item

Project: Report Type: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station All Items Date: Total Items: 4 4/27/2017

Log: G	G Submittal					Day	Days Open Calculated by: Calendar Days since date Initially Created	ed by: Calendar	Days since	date Initially	Created
Section	Item#	Description	Supplier or Manufacturer	Date from Sub	Date from Carothers	Review by	Review by Arch	Return to	Action	B-1-C	Days Open
084113 Aluminum- Framed Entrances And Storefronts	084113-11	Transmittal #644 Logo sign wall color chart	Clearvue Glass Company	04/11/2017	04/20/2017					Cons	16
085113 Aluminum Windows	085113-5	Transmittal #667 Fire rated window color chart	Clearvue Glass Company	04/21/2017	04/27/2017					Cons	6
211320.0020 Foam Fire Extinguishing For Aircraft Hangars	211320.002 0-18	Transmittal #656 AFFF discharge tank drawings, installation manual, buoyancy calcs, etc	Charles Deweese Construction	04/12/2017	04/17/2017					Cons	15
263213.0020 Single Operation Generator Sets	263213.002 0-5	Transmittal #668 Single operation generator sets engine and generator test	TEXCAP	04/25/2017	04/26/2017					Cons	N



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 99 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 5/4/2017

Name:	Organization/Company Name:	Phone Number:	Email:	
(b) (6)	Carothers Construction NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC NAVFAC			6



Fax: (662) 234-3292

# Carothers/NAVFAC Weekly Meeting #99

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

May 4, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

# Agenda:

# I. Safety (b) (6)

- a) 255 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Five Hundred Eighty-Three (583) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 05/02/2017
- f) Deficiency Log
  - A total of Two Hundred Fifty-Four (254) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:

Tex Cap – Single Operation Generators (Submitted 05/03/2017)

- h) AHA/Activities about to start:
  - DeWeese AFFF Tank Re-installation AHA approved (Awaiting approvals)
- i) Weekly Safety Meeting Topic
  - PPE
  - Electrical Rooms/Panels
  - Site Clean Up(Admin Bldg)
  - Site Speed Limit



Fax: (662) 234-3292

### II. Quality Control (b) (6)

#### a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

#### c) Upcoming Preparatory Meetings:

- Solid Surface
- Finish carpentry
- Carpet
- Resilient Flooring
- Fence re-prep

#### d) Upcoming Initial Meetings:

- Bridge Crane-Will be scheduled once date that crane installer will be on site is confirmed.
   Approximately May 22nd
- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed, will schedule once initial tests are completed and before devices are installed. -TBD
- Sump Pumps
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed

#### e) General Quality Control Items:

- NAVFAC- please ask ATSI/MCAS, whoever their contract is with, to request that BJWSA and SCE&G update as-builts in my office or provide to NAVFAC, and we will incorporate them into our As-Built packages. <u>BJWSA Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either company
- Terracon-Scheduled to witness bedding installation and recommendations for AFFF tank once drawing issues are resolved
- Startup procedures, checklists, etc from HVAC contractor for mechanical and plumbing equipment received and submitted. Discussing submittal requirements with DOR for items that are included in commissioning
- Revised commissioning plan submitted to NAVFAC on 05/03/17. AHU startup took place on 05/02/17
- Duct installation Discrepancy in exposed ceiling areas; DOR sent letter regarding installation. Randy to send in CO
- AFFF tank Information sent to DOR for revised drawings and elevations for tank
  installation based on manufacturer's recommendations. Installation will be per
  manufacturer's instruction booklet. Tank removed from hole and recertification received
  from manufacturer. Revised submittal submitted and awaiting government approval.
  AFFF tank installation coordination taking place with DOR based on NAVFAC comments
  and response to MOD 06. Information will be sent to NAVFAC once it is received from
  DOR.
- Sprinkler installation issues with subcontractor were noted during overhead inspections. Work will be completed and re-inspected. Update: Awaiting sprinkler sub on site to finish work. Should be on site the week of May 8th



Fax: (662) 234-3292

• Accent wall paint colors (b) (6) to confirm intent on Drawings I-106-I-109. Awaiting revised drawings from STOA

- Coordination taking place with crane subcontractor and electrical and HVAC subs for work in hangar. Revised drawings forthcoming from crane sub for submittal
- SF-6 switch testing not complete. Will schedule once loop is complete and new wire
  pulled and in place. Will coordinate outage with NAVFAC once a date is provided for
  outage by subcontractor. Control curves and information on surge arrestors sent to
  NAVFAC this week.
- QC tests to be scheduled with Preferred Materials and third party testing agency. Will send
  Outlook invite once a time is received and confirmed.
- Solar water heating pressure test to be conducted next week. Awaiting calibrated gauge. Will schedule with NAVFAC once a specific date and time is determined.
- · Hangar light installation coordination taking place
- Awaiting gas piping FACTORY test results per API Std 598 and API Std 607 from manufacturer. Will send once received.
- Coordination meeting requested on 04/26/17 with base communications office. Awaiting revised drawing from base communications

#### **SAPF Issues**

- Ongoing photo documentation of SAPF construction.
- Coordination taking place for north wall in Room #232 security office Inspection took place on 05/04/17 at 9 AM
- Holes made after overhead inspection to be sealed
- Sprinkler piping bracing to be installed per plans

#### Area B:

None

#### Ready Room:

No issues

#### III. RFIs (Carrie Pinder):

- a) Outstanding RFIs Government
  - RFI #122 Landscape change at south side of parking garage
  - RFI #123 Landscape change at NW side of parking lot
  - RFI #124 Landscape change adjacent to box culvert
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - None
- d) Outstanding RFVs
  - None



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

#### Submitted Awaiting Approval:

 PC-035 – Unforeseen condition. Additional material above original quote. Revision sent to NAVEAC.

#### In Development:

NONE

#### Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - New Storm Inlet protection bags on order to replace existing. Will be installed upon arrival
  - Concrete washout pit to be reworked after AFFF tank is installed

#### V. Schedule (b) (6)

See Attached Schedule

## Administrative (b) (6)

- AA storm drain line (Delayed until June)
- Redzone Meeting 6/6/17
- O & M training

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Report Type:

Open Items

Project:

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Days Open Calculated by: Calendar Days since date Initially Created

Date:

Total Items: 18 5/03/2017

	110	106	105	103	101	93	90		89		87	82	75		ξ	Item#	Log:
	Various exterior windows throughout admin area	On site within project limits	Hangar- east/west end	second floor railing . South elevation	2nd floor elevator threshold	Roof Hatch Safety Railing	Room 131 Water Room		Structure 11D		Chiller Location	First Floor Corridor Cable Tray	East Elec Room#111			Location BOX CULVERT	Re-Work Log
_	Weather stripping and sill caps not installed correctly	Red Lines-As-Builts for all work under FEAD/NAVFAC	caged ladders missing bolts at feet and vertical legs	railing bent	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached		Storm Pipe not cut flush with structure and parged	damaged by Storm- tiying debris may be the cause for this	Hurricane Mathew- Chiller	Overspray from painters will need to be removed from cable tray	No Surface prep before applying paint to steel			Description Cracked Mortar	
																Created By	
																Responsible Party	
	03/31/2017	00/01/2017	03/34/3047	04/11/2017	03/34/2017	02/24/2017	01/31/2017	04/31/2017	12/16/2016		11/22/2016	09/16/2016	08/09/2016			11/06/2015	
	New	N NOW	New	New	Now Y	Now	New W	New	New		New	New	New			Fix Not Accepted	O Control
		BJWSA with no response or action taken.	previoulsy asked both NAVFAC/SCE&G/and	corrected	(b) (6) will notify QC dept once	Date entered is date found / damaged	date entered is date found	Date entered is date found	<ul> <li>QCM will inpsect all martinoles upon cossour and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.</li> </ul>			und of response	date entered is date found	entire installation	remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning	Work has been completed,QC inspections were held and deficient areas were	Comments
		48	56	56	57	97	139	140	;	146	101	107	239	281		558	Days Open



Open Items

Project: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Days Open Calculated by: Calendar Days since date Initially Created

Date:

5/03/2017

Total Items: 18

	117	116		115	114	113	- 1	112		Log:
Ston way wans	Vestibule and	Room 106 top of walls	Communication rooms	Various locations -	East side of parking garage	Parking Lot	throughout 2nd floor	Various room		Re-Work Log
	Primer applied to walls not finished to Level 5	Gypsum board wall supports on south wall exposed	not UL labeled	Fire rated comm backboard	Light pole base on east side of parking garage not level	Handicap sidewalks do not meet ADA requirements	not set correctly and are creating small gaps at edges of ceiling grid	HVAC grills in ceiling grid are	Description	
									Created By	
									Responsible Party	
	05/31/2017	02/16/60	05/24/2017	05/31/2017	05/19/2017	04/21/2017		04/19/2017	Due Date	
	New	400	Now	New	New	New		New	Status	
									Comments	Cays Sport Superior - 1
		20	14		14	20	27	3/	Days Open	

www.submittalexchange.com



Report Type:

Total Items: 5

Date: 5/03/2017

Project: St	Beaufort, SC Aircraft Station	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station				Dave	Dave Open Calculated by: Calendar Days since date Initially Created	ad bv: Calendar	Davs since	date Initially	itially Created
Log: G	G Submittal					50)					
Section	Item#	Description	Supplier or Manufacturer	Date from Sub	Date from Carothers	Review by Cons	Arch	Sub	Action	B-1-C	Open 2
019113.0025 General	019113.002 5-2	Transmittal #654 General commissioning requirements for construction	MEP Southeast	05/01/2017	05/03/2017					0	1
Commisioning aquirements For		commissioning plan, prefunctional checklists, and FPTs									
084113 Aluminum- Framed Entrances	084113-11	Transmittal #644 Logo sign wall color chart	Clearvue Glass Company	04/11/2017	04/20/2017					5	7
And Storeironis 085113 Aluminum Windows	085113-5	Transmittal #667 Fire rated window cotor chart	Clearvue Glass Company	04/21/2017	04/27/2017					Cons	21
211320.0020 Foam Fire Extinguishing	211320.002 0-18	Transmittal #656 AFFF discharge tank drawings, installation manual, buoyancy calcs, etc	Charles Deweese Construction	04/12/2017	04/17/2017					9	, !
263213.0020 Single Operation Generator	263213.002 0-5	Transmittal #668 Single operation generator sets engine and generator test	TEXCAP	04/25/2017	04/26/2017					9	,

News	Organization	Email	Initial
(b) (6)	CCI CCI CCI CCI CCI CCI CCI FEAD FEAD FEAD FEAD FEAD FEAD	(b)	(6)

5/18/2017


Owner's Meeting #101 canceled.



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 162 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 5/25/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #102

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

May 25, 2017-1:00 pm - 2:00 pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

I. <u>Safety</u>(b) (6)

- a) 284 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Five Hundred Ninety-One (591) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 05/25/2017
- f) Deficiency Log
  - A total of Two Hundred Sixty-One (261) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:

Elmore Millwork – Cabinet & Counter Installation (returned to sub for corrections)

- h) AHA/Activities about to start:
  - Florida Library Designs Pilot Lockers
  - Floor Coatings Epoxy Floor Coating(Began 05/22/2017)
  - Regan Tile Carpet & Resilient Flooring(Submitted)
- i) Weekly Safety Meeting Topic
  - PPE
  - Red Taped Area
  - Electrical Rooms/Panels
  - Clean Up (Site/Building)

5/30/2017 – 1400 hrs. Truck gate will close daily. All traffic will go to Main Gate unless previous Arrangements have been made through Pete Robson, NAVFAC.



Fax: (662) 234-3292

### II. Quality Control (b) (6)

#### a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

#### c) **Upcoming Preparatory Meetings:**

- Solid Polymer Fabrications
- Finish Carpentry Elmore Millwork and Florida Library Design
- Carpeting
- Resilient Flooring
- Fence re-prep Scheduled for May 30<sup>th</sup>
- Spray applied fireproofing Prep wk of 5/30. Start wk of 6/5

#### d) Upcoming Initial Meetings:

- Interior Fire Alarm and Mass Notification- routing has been checked, Megger test performed Premier Fire
- Sump Pumps
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed

#### e) General Quality Control Items:

- NAVFAC- Please request that BJWSA and SCE&G update as-builts in QC office or provide to NAVFAC and we will incorporate them into our As-Built packages. <u>BJWSA</u> <u>Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either <u>company</u>
- Site visit by DOR, mechanical engineer, fire protection engineer, and electrical engineer on May 24<sup>th</sup>. Reports to follow noting items discussed
- MOD 06 to be issued next week
- ABM will be on site on Saturday, May 27<sup>th</sup> to perform final electrical testing during outage scheduled

#### SAPF Issues

- Ongoing photo documentation of SAPF construction
- Above ceiling wall penetration inspection held on 05/19/17

#### Area B:

None

#### Ready Room:

No issues

### III. <u>RFIs</u> (b) (6)

- a) Outstanding KFIs Government
  - RFI #126 Dielectric break from comm room through G line wall
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #234 Solar water piping
  - RFI #235 Drain lines in mechanical room
- d) Outstanding RFVs
  - None



Fax: (662) 234-3292

QC Note: Terminations - contact base comm...

#### IV. RFP's/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

 PC-035 – Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC.

#### In Development:

- PC-044 BJWSA Utility conflict Provided to subcontractor. Awaiting Proposal.
- PC-045 Raising of existing Manhole Cover and Frame in Parking Lot. Awaiting Proposal from Subcontractor. \* Send to (b) (6)

#### Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - New Storm Inlet Protection installed on 8 drop inlets

# V. <u>Schedule</u> (b) (6)


See Attached Schedule

# Administrative (b) (6)

- AA storm drain line (start work 1 June)
- Next Redzone Meeting 6 June
- O & M training
- Electrical outage

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.





Date:

5/25/2017

Total Items: 16

Report Type: Open Items

Project:

Re-Work Log

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Days Open Calculated by: Calendar Days since date Initially Created

114	113	110	=	=	=	=	93	90	89	87	75	ta.	<u> </u>
4	Ξ	5	106	105	103	101	ω	0	9	7	51	35	Item#
East side of parking garage	Parking Lot	Various exterior windows throughout admin area	On site within project limits	Hangar- east/west end	second floor railing . South elevation	2nd floor elevator threshold	Roof Hatch Safety Railing	Room 131 Water Room	Structure 11D	Chiller Location	East Elec Room#111	BOX CULVERT	Location
Light pole base on east side of parking garage not level	Handicap sidewalks do not meet ADA requirements	Weather stripping and sill caps not installed correctly	Red Lines-As-Builts for all work under FEAD/NAVFAC	caged ladders missing bolts at feet and vertical legs	railing bent	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached	Storm Pipe not cut flush with structure and parged	Hurricane Mathew- Chiller damaged by Storm- flying debris may be the cause for this	No Surface prep before applying paint to steel	Cracked Mortar	Description
												(b)	Created By
												(6)	Responsible Party
05/19/2017	04/21/2017	03/31/2017	03/31/2017	03/31/2017	04/17/2017	03/31/2017	02/24/2017	01/31/2017	12/16/2016	11/22/2016	08/09/2016	11/06/2015	Due Date
New	New	New	New	New	New	New	New	New	New	New	New	Fix Not Accepted	Status
			previoulsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.		orrected will notify QC dept once	Date entered is date found / damaged	date entered is date found	Date entered is date found	QCM will inpsect all manholes upon closeout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.		Date entered is date found	Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.	Comments
42	49	70	78	78	79	119	161	162	168	219	303	580	Days Open



Report Type: Open Items

Project: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Log:

Re-Work Log

Date: Total Items: 16 5/25/2017

Days Open Calculated by: Calendar Days since date Initially Created

119	116	115	Item#
Mechanical Room 2nd Floor Room 228	Room 106 top of walls	Various locations - Communication rooms	Location
Refrigerant line kinked, South wall	Gypsum board wall supports on south wall exposed	Fire rated comm backboard not UL labeled	Description
			Created By
		6	Resnonsible Party
05/22/2017	05/31/2017	05/31/2017	Due Date
New	New	New	Status
			Comments
17	36	36	Days Open



Date:

5/25/2017

Report Type: Report By

All Items

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air

Ι,	Action	Return to	Pavia	Review by	Data from	Data from	Supplier or	Description	ltern#	Section	
edate Initially Created	Days since	Salculated by: Calendar Days since date Initial!	nen (	Davs O					G Submittal	Log:	
									Station	i iojeci.	
Total Items: 2							Manne Corps Air	Beautort, SC Aircraft Maintenance Hanger at Marine Corps Air	Beautort, SC F	Droinet	


Government Safety Requirements for Design-Build 013526,0525 Government Safety 013526.0525 Requirements for Design-Build Section 013526.052 5-323 013526.052 5-322 #11911 SUbmittal #678 AHA ELmore Millwork for Cabinet/Counter Installation 05/23/2017 Submittal #677 EMR/Dart Rate for ELmore Millwork 05/23/2017 Description Elmore Millwork Elmore Millwork Manufacturer Sub 05/23/2017 05/23/2017 05/23/2017 Carothers 05/23/2017 Cons Arch Sub Cons Cons Open 2



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 103 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 6/1/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #103

**Project:** 

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

June 1, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

#### I. Safety (b) (6)

- a) 291 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Six hundred (600) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 1 new First Aid has been reported since our last meeting. Cut finger Ricky Cox Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 05/31/2017
- f) Deficiency Log
  - A total of Two Hundred Sixty-Four (264) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:

N/A

#### h) AHA/Activities about to start:

- Florida Library Designs Pilot Lockers
- AA Storm Line/Communications tie in DeWeese & Tex Cap
- Diamond Engineering Spray Applied Fireproofing
- i) Weekly Safety Meeting Topic
  - Hydration/Dehydration
  - Smoking on Site
  - Site Speed Limit



Fax: (662) 234-3292

# II. Quality Control (b) (6)

a) Re-Work Logs

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G Submittal"</u> Tab:

See Attached

#### c) Upcoming Preparatory Meetings:

- Solid Polymer Fabrications
- Finish Carpentry Elmore Millwork and Florida Library Design
- Carpeting
- Resilient Flooring
- Spray applied fireproofing-Scheduled for June 12th

#### d) **Upcoming Initial Meetings:**

- High security chain link fences Scheduled for June 1 at 2 PM
- Interior Fire Alarm and Mass Notification-Scheduled for June 1 at 2:30 PM
- Sump Pumps-Scheduling around elevator training
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed

#### e) General Quality Control Items:

- NAVFAC- Please request that BJWSA and SCE&G update as-builts in QC office or provide to NAVFAC and we will incorporate them into our As-Built packages. <u>BJWSA</u> <u>Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either <u>company</u>
- Site visit by DOR, mechanical engineer, fire protection engineer, and electrical engineer on May 24<sup>th</sup>. Awaiting site visit reports and revised drawings and details from site visit discussions
- MOD 06 to be issued by the end of this week or next
- ABM was on site to perform testing on cable that was installed. Issue found during install and RFI sent to government. Awaiting response
- Fire alarm Kingfisher transmitter antenna location Verification?

#### **SAPF Issues**

- Ongoing photo documentation of SAPF construction
- Di-electric break from comm room to mechanical room for split system

#### Area B:

None

#### Ready Room:

No issues

#### III. RFIs (b) (6)

- a) Outstanding RFIs Government
  - RFI #126 Dielectric break from comm room through G line wall; Needs to be readdressed. Discussed in QC bi-weekly meeting with Lane and Walker White
  - RFI #128 6" conduit from GSE-P465 manhole
- b) Outstanding RFIs SAPF
  - None



Fax: (662) 234-3292

- c) Outstanding RFIs STOA
  - RFI #234 Solar water piping
  - RFI #235 Drain lines in mechanical room
- d) Outstanding RFVs
  - None

#### IV. RFPs/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

- PC-035 Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC
- PC-045 Raising of existing Manhole Cover and Frame in Parking Lot. Submitted 5/25 In Development:
  - PC-044 BJWSA Utility conflict Awaiting revised Proposal from CDCI.

#### Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Concrete washout pit will be replaced to support concrete placement for remainder of roadway.

#### V. Schedule (b) (6)

See Attached Schedule

#### Administrative (b) (6)

- AA storm drain line (start work 1 June)
- Next Redzone Meeting 6 June
- O & M training
- Electrical outage

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.

Report

Report Ty

Project: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Log:

Re-Work Log

Total Items: 20

Date:

6/01/2017

Days Open Calculated by: Calendar Days since date Initially Created

114	113	110	106	105	103	101	93	90	89	87	75	35 Item #
East side of parking garage	Parking Lot	Various exterior windows throughout admin area	On site within project limits	Hangar- east/west end	second floor railing . South elevation	2nd floor elevator threshold	Roof Hatch Safety Railing	Room 131 Water Room	Structure 11D and 10D	Chiller Location	East Elec Room#111	Location BOX CULVERT
Light pole base on east side of parking garage not level	Handicap sidewalks do not meet ADA requirements	Weather stripping and sill caps not installed correctly	Red Lines-As-Builts for all work under FEAD/NAVFAC	caged ladders missing bolts at feet and vertical legs	railing bent	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached	Storm Pipe not cut flush with structure and parged	Hurricane Mathew-Chiller damaged by Storm-flying debris may be the cause for this	No Surface prep before applying paint to steel	<u>Description</u> Cracked Mortar
												Created By
												Responsible Party
05/19/2017	04/21/2017	03/31/2017	03/31/2017	03/31/2017	04/17/2017	03/31/2017	02/24/2017	01/31/2017	12/16/2016	11/22/2016	08/09/2016	<u>Due Date</u> 11/06/2015
New	New	New	New	New	New	New	New	New	New	New	New	Status Fix Not Accepted
			previoulsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.		(b) (6) will notify QC dept once corrected	Date entered is date found / damaged	date entered is date found	Date entered is date found	QCM will inpsect all manholes upon doseout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.		Date entered is date found	Comments  Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.
49	56	777	85	85	86	126	168	169	175	226	310	Days Open 587



124 123 122 121 Item# Log: Project: 120 116 115 Report Type: side of corridor Behind comer guard and marker boards Block wall on NW throughout admin Various block walls room East side of hangar -1st floor mech/water system Counterpoise Room 106 top of Communication rooms Various locations -Location Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Open Items Re-Work Log Block wall on northwest side of corridor concave approx expansion joints and columns Cracks in block walls close to comer guards and markerboards Walls not painted behind Block cracked from 1st floor to insulated counterpoise - Must not be Insulated cable used for on south wall exposed Gypsum board wall supports 2nd floor where column exists not UL labeled Fire rated comm backboard Description Created By Responsible Party 06/23/2017 06/23/2017 06/23/2017 06/23/2017 06/02/2017 05/31/2017 05/31/2017 Due Date New New New New New New Status Days Open Calculated by: Calendar Days since date Initially Created Comments Date: Total Items: 20 Days Open 6/01/2017 43 43



www.submittalexchange.com

# CAROTHERS CONSTRUCTION SCHEDULE

			GAR	ED	PAINT GARAGE	
			ADMIN	ED	PAINT FIRST FLOOR	28190
			ADMIN	ED	PAINT SECOND FLOOR	29180
WAITING			ADMIN	PANHANDLE	ELEVATOR	29450
			ADMIN		MILLWORK SECOND FLOOR	29240
			ADMIN		MILLWORK FIRST FLOOR	28240
			HANG	CINCINNATI	BRIDGE CRANE	27120
FINAL CA			ADMIN	CLEARVIEW	EXT WINDOWS	26090
			ADMIN	CAROTHERS	CEILING TILE SECOND FLOOR	
			HANG	CAROLINA	TRANSLUCENT WALL PANELS	27060
			SITE	WALDROP	SIDE WALKS	
			SITE	WALDROP	ROADWAY CONCRETE AROUND HANGAR	
			ADMIN	HARRIS	CONTROLS STARTUP	
			SITE	TEXCAP	COMM	
			HANG	TEXCAP	OVERHEAD HANGAR	
			SITE	TEXCAP	UNDERGROUND FOR SECURITY FENCE	
			SITE	BRABHAM	SECURITY FENCE AROUND PARKING GARAGE	40050
			SITE	SEED	SOD	40040
			SITE	DEWEESE	GRADE AND BASE FOR ROAD AROUND HANGAR	
			SITE	DEWEESE	FINAL GRADE ON SITE	
OIL WATE			SITE	DEWEESE	AFFF TANK	20230
INSTRUCT			SITE	DEWEESE	AA STORM LINE AND ASSOCIATED STRUCTURES	20020
7	1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19	29 30 31 1	Area	Responsibility	Activity Description	ACTIVITY ID
	JONET JONET	. <				
		V A A A	ļ			

# P465 HANGAR BEAUFORT, SC

# CAROTHERS CONSTRUCTION SCHEDULE


Activity ID	Activity Description	Responsibility	Area	MAY TH F S S	M T W THF S S M T W THF S S M	2
				29 30 31 1 2 3	4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19	9
	OVERHEAD HANGAR	WW	HANG			
THE REPORT OF THE PROPERTY OF	COOLING PIT ACCU	WW	HANG			
	BGSE ACCU CONTROLS	BGSE	HANG			
28210	FLOORING FIRST FLOOR	REGAN	ADMIN			
29220	FLOORING SECOND FLOOR	REGAN	ADMIN			
28160	CERAMIC FIRST FLOOR	REGAN	ADMIN			



P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

#### P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 104 **CAROTHERS/NAVFAC SIGN-IN SHEET**

DATE: 6/8/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #104

Project:

P465 Aircraft Hangar

**Contract:** 

N69450-14-D-1266

Date:

June 8, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

### I. <u>Safety</u>(b) (6)

- a) 298 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Six hundred fourteen (614) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 05/31/2017
- f) Deficiency Log
  - A total of Two Hundred Sixty-Eight (268) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:

Resilient flooring

Carpet

#### h) AHA/Activities about to start:

- Florida Library Designs Pilot Lockers
- AA Storm Line/Communications tie in DeWeese & Tex Cap
- Diamond Engineering Spray Applied Fireproofing

#### i) Weekly Safety Meeting Topic

Step ladder use and storage.

Speed limit

Informed workers of intermittent power outages during generator testing



Fax: (662) 234-3292

#### II. Quality Control (b) (6

#### a) Re-Work Log:

See Attached

# b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> <u>Submittal" Tab:</u>

See Attached

#### c) Upcoming Preparatory Meetings:

- Solid Polymer Fabrications
- Finish Carpentry Elmore Millwork and Florida Library Design
- Spray applied fireproofing

#### d) Upcoming Initial Meetings:

- High security chain link fences Scheduled for June 12th at 1:30 PM
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed
- Resilient Flooring-Scheduled for June 8th
- Carpeting

#### e) General Quality Control Items:

- NAVFAC- Please request that BJWSA and SCE&G update as-builts in QC office or provide to NAVFAC and we will incorporate them into our As-Built packages. <u>BJWSA</u> <u>Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either <u>company</u>
- Site visit by DOR, mechanical engineer, fire protection engineer, and electrical engineer on May 24<sup>th</sup>. Site visit report received. Reviewing comments from report.
- Still awaiting MOD 06 from STOA
- Fire alarm Kingfisher transmitter antenna location Awaiting information from Premier Fire and TEXCAP before a location is given by govt
- Crane testing
- O&M's How are they to be turned in? One at a time or all at once at the end of the project?

#### SAPF Issues

- Ongoing photo documentation of SAPF construction
- · Di-electric break from comm room to mechanical room for split system

#### Area B:

None

#### Ready Room:

No issues

#### III. RFIs(b) (6)

- a) Outstanding RFIs Government
  - RFI #126 Dielectric break from comm room through G line wall; Needs to be readdressed. Discussed in QC bi-weekly meeting with (b) (6)
  - RFI #127 Mechanical drain lines
  - RFI #128 6" conduit from GSE-P465 manhole. Forwarded onto (b) (6)
     TEXCAP for response
- b) Outstanding RFIs SAPF
  - None



Fax: (662) 234-3292

- c) Outstanding RFIs STOA
  - None
- d) Outstanding RFVs
  - None

#### IVRFPs/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

- PC-035 Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC
- PC-045 Raising of existing Manhole Cover and Frame in Parking Lot. Submitted 5/25

#### In Development:

- PC-044 BJWSA Utility conflict Awaiting revised Proposal from CDCI.
- PC-046 Epoxy flooring add RM 125. Awaiting quote from subcontractor.

#### Storm-water/Erosion Controls -

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - BMP's have been inspected and are working properly after large rain event

## V. Schedule (b) (6)

See Attached Schedule

## Administrative (b) (6)

- AA storm drain line
- Next Redzone Meeting, 13 June 2017
- O & M training

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



_		
(		
(		
Ţ	Ву	
	oort By	
	Report By	

Date: 6/08/2017 Total Items: 21 Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Report Type: Open Items Project:

i ojeci.		beduior, 30 Aircrait Maintenance nanger at Manne Corps Air Station	Maine Corps Air Station				lotal Items: 21	
Log:	Re-Work Log				_	Days Open Calculated by: Calendar Days since date Initially Created	Initially Created	
Item #	Location	Description	Created By Resnonsible Party	Due Date	Status	Comments	Days Open	
35	BOX CULVERT	Cracked Mortar	(9) (q)	11/06/2015	Fix Not Accepted	Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.	594	
75	East Elec Room#111	No Surface prep before applying paint to steel		08/09/2016	New	Date entered is date found	317	
87	Chiller Location	Hurricane Mathew-Chiller damaged by Storm- flying debris may be the cause for this		11/22/2016	New		233	
88	Structure 11D and 10D	Storm Pipe not cut flush wit structure and parged		12/16/2016	New	QCM will inpsect all manholes upon closeout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.	182	
06	Room 131 Water Room	Tanks damaged see photos attached		01/31/2017	New	Date entered is date found	176	
93	Roof Hatch Safety Railing	this color is safety yellow an on IFC plans, it is to match t roof color.		02/24/2017	New	date entered is date found	175	
101	2nd floor elevator threshold	Fire Rated Expansion Joint Material flashing is damage and will need to be replaced		03/31/2017	New	Date entered is date found / damaged	133	
103	second floor railing. South elevation	railing bent		04/17/2017	New	(b) (c) will notify QC dept once corrected	93	
105	Hangar- east/west end	caged ladders missing bolts feet and vertical legs		03/31/2017	New		92	
106	On site within project limits	Red Lines-As-Builts for all work under FEAD/NAVFAC		03/31/2017	New	previoulsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.	92	
110	Various exterior windows throughout admin area	Weather stripping and sill caps not installed correctly		03/31/2017	New		84	
113	Parking Lot	Handicap sidewalks do not meet ADA requirements		04/21/2017	New		63	
114	East side of parking garage	Light pole base on east side of parking garage not level		05/19/2017	New		26	
S.WWW	www.submittalexchange.com						Dozen 4 of 2	





	The second secon	
Report Ty	Report Type: Open Items	Date: 6/08/201
Project:	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	Total Items: 2
Log:	Re-Work Log	Days Open Calculated by: Calendar Days since date Initially Create

CONSTRUCTION INC.

Report Type:	Type: Open Items		la .				Date:	6/08/2017
Project:	Beaufort, SC Ai	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	arine Corps Air Station				Tote	Total Items: 21
Log:	Re-Work Log						Days Open Calculated by: Calendar Days since date Initially Created	ally Created
Item #	Location	Description	Created By Respons	Responsible Party	Due Date	Status	Comments	Days Open
115	Various locations - Communication rooms	Fire rated comm backboard not UL labeled	(H)		05/31/2017	New		90
116	Room 106 top of walls	Gypsum board wall supports on south wall exposed			05/31/2017	New		90
120	East side of hangar - Counterpoise system	Insulated cable used for counterpoise - Must not be insulated			06/02/2017	New		4
121	1st floor mech/water room	Block cracked from 1st floor to 2nd floor where column exists			06/23/2017	New		8
122	Behind corner guard and marker boards	Walls not painted behind corner guards and markerboards			06/23/2017	New		œ
123	Various block walls throughout admin area	Cracks in block walls close to expansion joints and columns			06/23/2017	New		89
124	Block wall on NW side of corridor	Block wall on northwest side of corridor concave approx 1/4"			06/23/2017	New		8
125	2nd floor admin through wall flashing	Trim back modified shelf angle east of the curtainwall uniformly			06/30/2017	New	Per discussion with STOA	-



Carothers Construction, Inc.

	6/08/2017	Total Items: 4	Ily Created	Days	9	59	38	80
	Date:	Tot	e date Initia	B-1-C	Cons	Cons	Cons	Cons
			r Days since	Action				
			ted by: Calendar	Return to Sub				
			Days Open Calculated by: Calendar Days since date Initially Created	Review by Arch				
			Day	Review b				
				Date from Carothers	06/07/2017	06/05/2017	06/07/2017	06/05/2017
				Date from Sub	06/02/2017	05/10/2017	05/01/2017	05/31/2017
				Supplier or Manufacturer	Metro Waterproofing	Premier Fire	Walker White	Cincinnati Crane
		Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station		Description	Transmittal #681 Expansion joint between admin and hangar	Resubmittal of Transmittal #574.3 Foam fire Extinguishing for aircraft hangars revised & Transmittal #574.4 Foam fire extinguishing for aircraft hangars revised disposal and containment plan	Transmittal #651 Non lubricated rotary screw air compressor startup and testing	Transmittal #680 Bridge crane hook and wire rope certificate, magnetic particle report
	All Rems	Beaufort, SC Aircra Station	G Submittal	tem#	079200-5	211320.002 0-23	221519.192 0-3	412213.15-4
Report	Report Type: All	Froject: Be	Log: G	Section	079200 Joint Sealants	211320,0020 Foam Fire Extinguishing For Aircraft Hangars	221519.1920 Nonlubricated Rotary Screw Air Compressors (100HP And Larger)	412213.15 Bridge Cranes, Overhead Electric, Under Running

# CAROTHERS CONSTRUCTION SCHEDULE

											IIME: T:00 pm
				A. C.		June					
	Responsibility	Area	M T W	F S	SMT	W TH F	SS	M T W	W TH F S	S	REMARKS/ EXPECTED COMPLETION DATES
			2 9 9	8 9 10	11 12 13	3 14 15 16	17 18	19 20 21	22 23 24	4 25 26	
STRUCTURES	DEWEESE	SITE									
	DEWEESE	SITE									OIL WATER SEPERATER
	DEWEESE	SITE									
JND HANGAR	DEWEESE	SITE									
	SEED	SITE									
NG GARAGE	BRABHAM	SITE									
Y FENCE	TEXCAP	SITE									
	TEXCAP	HANG									
	TEXCAP	SITE									
	HARRIS	ADMIN									
HANGAR	WALDROP	SITE									
	WALDROP	SITE									
ANELS	CAROLINA	HANG									
LOOR	CAROTHERS	ADMIN									
	CLEARVIEW	ADMIN									FINAL CAULKING
	CINCINNATI	HANG									
JOR		ADMIN									
_00R		ADMIN									
	PANHANDLE	ADMIN									WAITING ON FINAL TEST
OR	ED	ADMIN									
R	ED	ADMIN									
	ED	GAR									

DATE: 5-29-17 TIME:1:00 pm

# CAROTHERS CONSTRUCTION SCHEDULE

				I IME: T:00 pm
			June	
	Responsibility	Area	M T W TH F S S M T W TH F S S M T W TH F S S M	REMARKS/ EXPECTED COMPLETION DATES
			5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26	
W,	WW	HANG		
	ww	HANG		Flushing lines
STI	BGSE	HANG		
OR	REGAN	ADMIN		
OOR	REGAN	ADMIN		
JR	REGAN	ADMIN		

P465 Aircraft Maintenance Hanger & Parking Garage - Owner Modification Log (Job #513)

Closed Navy disapproved submitted proposal and issued c	N/A N/A	0 N/A	104,889.00	2/19/2015 \$ 104,889.00 \$ 104,889.00 N/A \$ 14,214.00 \$ -	\$ \$	2/19/2015 \$ N/A \$	2/19/2015 N/A	2/18/2015 N/A	N/A	1/8/2015 2/14/2015 2/18/2015 12/17/2014 N/A N/A	11/22/2014 Not specified 12/17/2014	N/A 11/22/2014	al in Ancillary
Closed	N/A	0		104,889.00 \$	69	2/19/2015	2/19/2015	2/18/2015	2/14/2015	5107/8/1	N/A	N/A	EV. I
Navy disapproved submitted proposal and issued of 12/23/14	N/A	N/A		331,474.00 \$	69	N/A	N/A	N/A	N/A	12/17/2014	11/14/2014 Not specified 12/17/2014	11/14/2014	langes
Closed	N/A	0	63,336.00	63,336.00 \$	69	4/16/2015 \$	4/13/2015	12/22/2014	•	3/10/2015	N/A	N/A	
Remarks	New Contract Date	Add'I	pproved Price	Submitted Price Approved Price		Date Owner Signed	Date SF-30 Returned to NAVFAC	Date SF-30 Received	PCO Approval Date	PCO Submission Date	RFP Due Date Submission Date	Date RFP Received	
							6/8/2017						
					_	-D-1266-000	ct Number: N69450-14-D-1266-0001	Contract Numb	ပိ				

RAP Dee Dee Dee Dee Dee Dee Dee Dee Dee De	-				***************************************											
NA		Date RFP Received		PCO Submission Date	PCO Approval Date	Date SF-30 Received	Date SF-30 Returned to NAVFAC	Date Owner Signed			pproved Price	Add'l Days	New Contract Date	Remarks	File No.	Job Cost Chang
1717-101   NA   NA   NA   NA   NA   NA   NA   N		N/A	N/A	3/10/2015		12/22/2014	4/13/2015	4/16/2015	69	-		0	N/A	Closed	3	9
122001   NA   NA   1070014   NA   1070015   2102015   2102015   2102015   2102010   2102010   2102010   NA   NA   NA   NA   NA   NA   NA   N	ges	11/14/2014		12/17/2014	N/A	N/A	N/A	N/A				N/A	N/A	Navy disapproved submitted proposal and issued comments on		2
1717031	REV. 1	N/A		1/8/2015	2/14/2015	2/18/2015	2/19/2015	2/19/2015		-		0	N/A	-		N/A
1217015   NAA   30242015   12242014   12242014   12242014   21122015   NAA   30242015   12242014   12242014   12242015   12242014   12242015	Ancillary	11/22/2014	100	12/17/2014	N/A	N/A	N/A	N/A	4	-		N/A	N/A	Navy disapproved submitted proposal and issued comments on		Yes
12172015   NAA   22242016   21132016   21132016   21132016   21132016   21132016   NAA   22242016   21132016   NAA   22242016   21132016   NAA   22242016   NAA   NAA   22242016   NAA   222420	Ancillary		-				4304	TAN .	9			NIA	NA	12/23/14	9	N/A
17170015   NAA   3040015   .		N/A	N/A	12/23/2014	12/24/2014	2/13/2015	2/13/2015	2/14/2015	69	_		0	N/A	Closed	9	Yes
1212015   NA   3502015   NA   3502015   NA   3602015   NA   NA   NA   15022015   NA   NA   15022015   NA   NA   15022015   NA   15022015   NA   NA   NA   NA   NA   NA   NA   N		1/21/2015	N/A	3/24/2015	1	1	-	1	<b>S</b>			N/A	N/A	Navy rejected credit because no profit was offered back to the Government	6	N/A
1212-015   NAA   SAGDIS   SA	-	1/21/2015	N/A	3/30/2015		•	•					N/A	N/A	Navy rejected credit proposal because no Field Office Mark-up	0	A/N
1282015   NAA   1592015   2142015	2	1/21/2015	N/A	5/6/2015			1					NI/A	MIA	was provided to Government		UAT
1728/2015   NNA   31/12/2015   S. 20/12/2015   S. 20/12/20	416	1/28/2015	N/A	1/30/2015	2/14/2015	2/14/2015	2/16/2015	2/17/2015				0	N/A	Closed	6 8	, Vac
1782015   NNA   3182015		1/28/2015	N/A	3/12/2015	N/A	N/A	N/A	N/A	69			5	9/13/2015	Navy disapproved submitted proposal and issued comment on March 12, 2015. Disapproved time extension because it could		N/A
1782015   NAA   6032015   NAA   6032015   NAA   8032015   NA		N/A		3/18/2015	,	1	1	-	59	56,379.00	1	0	N/A	Awaiting annional from Navo	+	
14312015   NAA   3202015   3.70		1/28/2015		6/23/2015					89				N/A	Navy Approved	10	
10   20/2015   219/2015   219/2015   320/2	tion	1/31/2015		3/20/2015		1	ı	•		(13,720.00)		0	N/A	Navy rejected credit and directed to follow RFP requirements for 8" thick GAB Closed	==	No
29/2015         21/92015         41/2015         <	onal Filter	2/9/2015	2/18/2015	2/26/2015	3/20/2015	3/20/2015	3/20/2015	3/20/2015	69			0	N/A	Closed	13	Yes
223/2015   Not specified   4/102015   4/10		2/9/2015	2/19/2015	4/1/2015	4/28/2015	4/28/2015	4/29/2015	5/1/2015	S	+	21,631.00	0	N/A	Closed	-	Vac
Machierised   Most specified   Most sp		2/9/2015	2/18/2015	3/10/2015	4/1/2015	4/1/2015	4/1/2015	•	s	$\vdash$	13,867.00	0	N/A	Closed	15	Yes
Unsolcitical Not specified   4/10/2015   S/82/2015	risions	2/23/2015	8	6/18/2015	7/7/2015	-				-	35,500.00	0	N/A	Closed	17	
4/29/2015   Not specified   4/20/2015   5/82/2015   5/82/2015   S/82/2015		Unsolicited		4/16/2015		1 1					1	45	1	Disapproved	19	N/A
129/2015   Not specified   4/202015   S/82015   S/8201		4/29/2015		1				-		-	1,419,000.00	4	1 1	Disapproved	10	N/A
3/29/2015   Not specified   4/28/2015     S   18,947,00   S     NIA   NIA   NIA   NIA   NIA specified   4/28/2015   Not specified   4/28/2015   Not specified   1/15/2015   Not specified   1/15/2015   Not specified   NIS/2015   Not specified   NIS/2015   NIS/2015   NIS/2015   NIA	ring Wells		Not specified	4/20/2015	5/8/2015	5/8/2015			99	-	12,359.00	0	N/A	Closed	,	Y Y
3/29/2015   Not specified   715/2015   Str2015   Not specified   715/2015   Str2015   Not specified   715/2015   Str2015   S	ty.	3/29/2015		4/28/2015	,		1	•	59		•	N/A	N/A	Navy responded with comments on 4/28/15	30	MIA
1,000,000   1,00	kev. 1	3/29/2015										N/A	N/A	101.00	20	N/A
cised         57/2015         6/12/2015         6/13/2015         -         -         -         -         100,109,00         s         -         100,109,00         s         -         100,109,00         s         -         100,109,00         s         -         -         100,109,00         s         -         -         100,109,00         s         -         -         -         -         -         100,109,00         s         -	EV. 2	3/9/2015		7/15/2015	8/12/2015		-			199	(15,500.00)	0	N/A	Negotiated- Approved	20	
vised         57/12015         5/21/2015         6/24/2015         -         -         -         5         160,109.00         S         -         0         N/A           vised         57/12015         5/21/2015         7/15/2015         7/20/2015	stbank	5/7/2015		6/15/2015						-		100	1/3/2017	Awaiting Navy Approval	18	,
vised         5772015         5212015         7182015         7182015         7202015         7202015         7202015         7202015         7202015         7202015         7202015         7202015         7202015         7202015         7202010	nk Revised		5/21/2015	6/24/2015						+					52	
5/1/2015         5/21/2015         7/18/2015         -         -         -         -         8         226,251.00         \$         -         0         N/A           vised         5/7/2015         5/21/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         8         215,626.00         \$         215,626.00         0         N/A           5/26/2015         -         6/12/2015         -         -         -         8         215,626.00         \$         215,626.00         0         N/A           5/26/2015         -         6/12/2015         -         -         -         8         7,021.00         0         N/A           5/27/2015         -         10/12/2015         -         -         -         8         666,795.00         8         7,021.00         0         N/A           9/2/2015         -         10/12/2015         -         -         -         -         8         8/14,66.00         8         7,021.00         0         N/A           N/A         N/A         4/24/2015         -         -         -         -         8         8/14,66.00         8         7,021.00         0         - <td>nk Revised</td> <td></td> <td>25</td> <td>1</td>	nk Revised														25	1
vised         57/2015         5/21/2015         7/15/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2015         7/20/2010         0         N/A           5/20/2015         -         4/12/2015         -         -         -         5         39,761.00         \$         7,021.00         -	IN INCVISE		5/21/2015	7/8/2015	1	-	•	•			1	0	N/A	Submitted Awaiting Approval	25	
5/26/2015         -         6/12/2015         6/12/2015         -         -         5         39,761.00         \$ 35,000.00         -         -           5/27/2015         -         7/21/2015         -         -         \$ 7,357.00         \$ 7,021.00         0         N/A           5/29/2015         -         8/10/2015         -         -         -         \$ 666,795.00         \$ 7,021.00         0         N/A           9/2/2015         -         10/1/2015         -         -         -         \$ 861,603.00         \$ 750,009.00         36         -         -         -         -         36         -         -         -         -         -         -         36         - <td>nk Revised</td> <td></td> <td></td> <td>7/15/2015</td> <td>7/20/2015</td> <td>7/20/2015</td> <td>7/20/2015</td> <td>7/20/2015</td> <td></td> <td></td> <td>215,626.00</td> <td>0</td> <td>N/A</td> <td>Approved and Issued</td> <td>25</td> <td>Yes</td>	nk Revised			7/15/2015	7/20/2015	7/20/2015	7/20/2015	7/20/2015			215,626.00	0	N/A	Approved and Issued	25	Yes
\$1/2015         -         7,21/2015         -         -         8         7,357.00         \$         7,021.00         0         N/A           \$1/202015         -         8/10/2015         -         -         -         \$         666,795.00         \$         7,021.00         0         N/A           \$1/202015         -         -         -         -         \$         861,603.00         \$         - <td>ų</td> <td>5/26/2015</td> <td></td> <td>6/12/2015</td> <td>6/23/2015</td> <td></td> <td>£</td> <td>-</td> <td><b>⇔</b></td> <td><math>\vdash</math></td> <td>35,000.00</td> <td></td> <td>5</td> <td>Negotiated- Approved</td> <td>27</td> <td>Yes</td>	ų	5/26/2015		6/12/2015	6/23/2015		£	-	<b>⇔</b>	$\vdash$	35,000.00		5	Negotiated- Approved	27	Yes
\$1/20/2015         -		5/27/2015		7/21/2015			1		89	-	7,021.00	0	N/A	Approved Pending RH discussion with NAVFAC	28	,
9/2/2015         -         -         -         -         5         861,603.00         \$         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         36         -         -         36         -         -         36         -         -         -         36         780,009.00         36         TBD         -         -         -         8         116,819.00         \$         -         0         -         -         0         -         -         0         -         -         0         -         -         0         -		5/29/2015		8/10/2015	-	ı	1	1			•	•	1	Additional Comments requiring resubmission	30	
9/2/2015         -         1/25/2016         -         -         8         8/1,466.00         \$         750,009.00         36         TBD           N/A         N/A         4/24/2015         -         -         -         \$         176,819.00         \$         -         0         -           N/A         N/A         2/9/2015         -         -         -         \$         176,819.00         \$         -         0         -           8/7/2015         S/21/2015         -         -         -         \$         176,819.00         \$         -         0         -           8/7/2015         S/21/2015         S/21/2015         -         -         -         \$         10,000.00         \$         -         -         -         0         -         -         0         -         -         -         -         0         -         -         -         -         0         -         -         -         -         0         -         -         -         -         -         0         -         -         -         -         -         -         -         -         -         -         -         -         -		9/2/2015		10/1/2015		1	•	1			•	36	1	Awaiting Approval- Negotiations held 12/17	30	,
N/A         N/A         4/24/2015         -         -         -         8         176,819.00         \$         -         0         -           N/A         N/A         2/9/2015         -         -         -         \$         78,026.00         \$         -         0         -           8/7/2015         8/21/2015         8/21/2015         3/15/2016         -         -         \$         39,553.00         \$         -         -         0         N/A           8/27/2015         8/21/2015         3/15/2016         4/19/2016         \$         20,026.00         \$         20,026.00         0         N/A           8/25/2015         -         11/28/2017         -         12/27/2015         \$         22,247.00         0         N/A           9/1/2015         9/1/2015         11/24/2016         -         12/27/2015         \$         22,247.00         0         0         0		9/2/2015		1/25/2016	1		1	-			750,009.00	36	TBD	Modification was received to also include BJWSA Delay (24)	30	Yes
N/A   N/A   29/2015     -		N/A	N/A	4/24/2015	•	1		•			•	0	1	Letter Received from D. Herschberger Stating no merit to	7	1
8/7/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2015         8/21/2016         8/21/2016         8/21/2016         8/21/2010 <th< td=""><td>Docs</td><td>N/A</td><td>N/A</td><td>2/9/2015</td><td></td><td>1</td><td>1</td><td></td><td></td><td></td><td>ı</td><td>0</td><td>1</td><td>/15</td><td>12</td><td></td></th<>	Docs	N/A	N/A	2/9/2015		1	1				ı	0	1	/15	12	
8/7/2015         8/21/2015         3/15/2016         -         -         -         5         39,553.00         0         N/A           8/7/2015         8/7/2015         3/31/2016         4/19/2016         5         20,026.00         0         N/A           8/7/2015         N/A         6/7/2016         1/18/2017         24         N/A           8/7/2015         -         11/28/2016         1/18/2017         2/4/2016         5/2,247.00           9/1/2015         9/1/2015         11/24/2016         -         1/18/2017         -         1/18/2010		8/7/2015	8/21/2015	8/25/2015	.1	1	•		55		•		1	hat	33	
8/7/2015         8/21/2015         3/31/2016         4/19/2016         \$ 20,026.00         \$ 20,026.00         \$ 20,026.00         \$ N/A           8/7/2015         N/A         6/7/2016         4/19/2017         \$ 57/7/71.00         \$ - 24         N/A           8/25/2015         11/28/2016         11/18/2017         5 52,247.00         \$ 52,247.00         \$ 0.24.50.00	.01A	8/7/2015	8/21/2015	3/15/2016	1	1	•		S	39,553.00		0	N/A	Ongoing development between GC/DOR/SUB	33	
N/A 6/7/2016 - 24  - 11/28/2016 1/18/2017	, 01B	8/7/2015		3/31/2016	4/19/2016			4/19/2016		$\vdash$	20,026.00	0	N/A		33	· N
9/9/2015 11/24/2015 - 12/27/2015 12/2/2010 3 2/2/247/20 3 2/2/247/20 4 2/2/247/20 5 2/24/24/20 5 2/24/24/24/20 5 2/24/24/24/24/24/24/24/24/24/24/24/24/24		8/25/2015		6/7/2016	1/18/2017						00 745 63	24		ye	35	
	And in contrast of the last of	9/1/2015	9/9/2015	11/24/2015	-	1	12/22/2015	\$100/00/01	-	+	713 462 000			Mod. Issued but not accepted	35	

Yes

33 35 35 37

Approved Modification Issued Sub Quotes should be in this week Mod. Issued but not accepted Approved Modification Issued

0

(13,462.00)

(13,462.00) \$

12/22/2015 \$

12/22/2015

11/24/2015

9/9/2015

9/1/2015

ses

	L				\$3,972,680		\$9,006,542.09				-			and the second second second second second	
		Awaiting Quote from subcontractor				-								6/2/2017	
No		Submitted 5/25/2017	7/2/2017	0			3,154.00			,		5/25/2017	5/23/2017	5/16/2017	er
No		Time Impact Needed for submission to complete					85,869.00	\$				5/30/2017	5/23/2017	5/15/2017	rm Line
No	'	80 Day Time Extension	7/2/2017	70		-		5/1/2017	5/1/2017				N/A	N/A	
Yes	'	Mod. Issued	4/13/2017	15	5,677.00	8	5,677.00	4/10/2017	4/10/2017	1	4/10/2017	3/22/2017	Not specified	1/30/2017	n. Shops
1	'			∞	ı	8	3	+	•			3/2/2017	not specified	1/30/201/	Suops
,	'	Mod. Issued but not accepted		0	(25,605.00)			-	***	1	1/17/701/	0107/01/11	Not specified	1/20/2017	Change
	-	Approved	,	1	27,074.00			9/16/2016	9/16/2016	-	9107/6/6	9107/6/6	Not specified	0107/1/6	nades
No.		Revision Submitted per negotiations 11/4 w/ NAVFAC	1		15,000.00	+	-				- 0000	0107/4/110	Not specified	9/0/2010	-
		Mod. Issued	1			-	-	4/10/2017 \$	4/10/2017		4/10/2017	/107/6/1	Not specified	01/22/2016	
- Yes	Ľ	Mod. Issued	1	0	737,194.09	-	737,194.09	910	1	1	6/6/2016	9/3/2015		8/15/2014	
		Turned in to Don H. 3/9 in person RH				0						2/107/6/5		N/A	n Vault
-	5	Approved Modification Issued	1	0	46,503.00	es	-	-	1	1		6/14/2016	Not specified	4/22/2016	
-	5	Approved Modification Issued	1	0	9,561.00	0	-	-	1	1	6/29/2016	5/9/2016	Not specified	4/22/2016	For Piles
+	5	Approved	1	0	1,212.00	9	Adequate materials before	-		1		6/14/2016	Not specified	4/22/2016	doc
+	5	Approved	1	0	(11,222.00)	\$ (0	(7,095.00)	-	1	-	8/1/2016	5/2/2016	Not specified	4/22/2016	ets
-	4	Approved Modification Issued	1	0	5,598.00	9	5,598.00	-		1	6/30/2016	5/9/2016	Not specified	4/8/2016	G Footprint
		Approved	2/20/2017	5	381,000.00	8	\$ 381,000.00	9/16/2016	9/16/2016	'		7/26/2016	N/A	3/18/2016	
- 72		ved Revised Pricing. Working on Revised Schedule Impact with	3/2/2017	15	1	0	\$ 917,570.00		•	•	•	3/28/2016	N/A	3/18/2016	
40 Yes	4	30 Compensable Days / 34 Noncomp. / 7 Weather Days	2/15/2017	71	96,810.00	\$	\$ 536,756.00	2/16/2016		1	2/16/2016	11/9/2015	N/A	N/A	
47 -		Modification was issued unilaterally. Additional Costs associated with this Mod. will be submitted to the Government via REA.	TBD	TBD	•	↔	-	•	1	1	1	1	1	1/14/2015	
46 Yes	4	Approved Modification Issued	N/A	0	3,500.00	\$ 0	\$ 4,181.00		1			1/28/2016	N/A	12/16/2015	ole 01B
- 94	4	Revision Submitted	1			0	\$ 5,539.00		-	1	-	0107/87/1	N/A	17/10/7013	able
-		Approved Modification Issued	10/31/2015	19	1	-		11/30/2015 \$					A/N	N/A	sion
+	4	Approved Modification Issued	,	0	9,024.00	0	\$ 9,024.00	-	-	1	11/19/2015	10/28/2015	-	9/22/2015	
39 Vec	100	Approved Modification Issued	N/A	0	(3,847.00)	\$ (0	\$ (3,847.00)	-			1	10/14/2015		9/10/2015	
+		Approved Modification Issued	N/A		1		and the same of the same	+			9/11/2015	9/11/2015	9/11/2015	9/11/2015	gs)
10 N/A	_	Approved Modification Issued	N/A	>		A	•	C107/C/6	-			7717			

Projected Final Completion Date:

34,399,000.00 3,972,680.09 38,371,680.09


34,399,000.00 9,006,542.09 43,405,542.09



Fax: (662) 234-3292

# P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 105 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 6/15/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #105

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

June 15, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

I. <u>Safety</u>(b) (6)

- a) 304 Days worked with Two (2) recordable incidents.
- b) Site Safety Orientations to Date:
  - Six hundred twenty (620) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 06/13/2017
- f) Deficiency Log
  - A total of Two Hundred Seventy One (271) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:
  - Elmore Millwork
- h) AHA/Activities about to start:
  - Florida Library Designs Pilot Lockers
  - AA Storm Line/Communications tie in DeWeese & Tex Cap
  - Diamond Engineering Spray Applied Fireproofing
- i) Weekly Safety Meeting Topic

Step ladder use and storage.

Excavation safety



Fax: (662) 234-3292

II. Quality Control (b) (6)
a) Re-Work Edg.

See Attached

### b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

#### c) Upcoming Preparatory Meetings:

- Solid Polymer Fabrications
- Finish Carpentry Elmore Millwork and Florida Library Design
- Spray applied fireproofing 6/20 -ECS-3RD party test

#### d) Upcoming Initial Meetings:

- Carpeting Scheduled for 6/16/17
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed
- Resilient Flooring-Scheduled for June 8th

#### e) General Quality Control Items:

- NAVFAC- Please request that BJWSA and SCE&G update as-builts in QC office or provide to NAVFAC and we will incorporate them into our As-Built packages. <u>BJWSA Responded regarding As-Builts</u>, but SCEG has not. Still have not received from either company. Received email from breading SCEG as-builts. Will include not on drawings to contact SCEG for as-built conditions
- Still awaiting MOD 06 from STOA
- Fire alarm Kingfisher transmitter antenna location Kingfisher can transmit for mass notification system. Waiting on a call back from FPE to discuss. Per specs: FMCP shall be connected to the Government Furnished Government Installed base-wide mass notification interface panel. Refer to drawings for infrastructure required. When will this be installed?
- Crane testing-Testing and training took place this morning at 10 AM 7/6
- O&M's How are they to be turned in? One at a time or all at once at the end of the project? before project is complete all at one time.
- Structural and civil engineer were on site on June 13th. Report to follow. Structural
  engineer looked at cracks in blocks and has stated they are not structural problems. An RFI
  will be sent to him for an official response
- Premier Fire on site correcting deficiencies with sprinkler lines as noted during walk through with (b) (6) Will schedule a walk through once all items are complete

#### **SAPF Issues**

- Ongoing photo documentation of SAPF construction
- Di-electric break from comm room to mechanical room for split system

#### Area B:

None

#### Ready Room:

No issues



Fax: (662) 234-3292

### III. RFIs(b) (6)

- a) Outstanding RFIs Government
  - RFI #126 Dielectric break from comm room through G line wall: Needs to be readdressed. Discussed in QC bi-weekly meeting with (b) (6)
  - RFI #128 6" conduit from GSE-P465 manhole. Forwarded onto (b) (6)
     TEXCAP for response
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - None
- d) Outstanding RFVs
  - None

#### IV. RFPs/Change Orders:

(Please reference Owners Modification Log)

#### Submitted Awaiting Approval:

- PC-035 Unforeseen condition. Additional material above original quote. Revision sent to NAVFAC
- PC-045 Raising of existing Manhole Cover and Frame in Parking Lot. Submitted 5/25

#### In Development:

- PC-044 BJWSA Utility conflict Awaiting revised Proposal from CDCI.
- PC-046 Epoxy flooring add RM 125. Awaiting quote from subcontractor.

#### Storm-water/Erosion Controls -

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - BMP's have been inspected and are working properly after large rain event

### V. Schedule (b) (6)

See Attached Schedule

### Administrative (b) (6)

- AA storm drain line
- Next Redzone Meeting, 11 July 2017
- O&M training
- FF&E Re-schedule for 24 July

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Report Type: Open Items

Project:

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Re-Work Log

Date: 6/15/2017

Total Items: 23

Days Open	Comments	Chadent			
					8
y: Calendar Days since date initially Created	Days Open Calculated by				3

113 Parking 114 East sid garage		106 end 106 On s	103 se Sc	101 2n	93 Ro Ra	90 Ro Ro	89 Strui 10D	87 Ch	75 Ea Ro	Item# Lo 35 BC
Parking Lot  East side of parking	Various exterior windows throughout admin area	Hangar- east/west end On site within project limits	second floor railing . South elevation	2nd floor elevator threshold	Roof Hatch Safety Railing	Room 131 Waler Room	Structure 11D and 10D	Chiller Location	East Elec Room#111	Location BOX CULVERT
meet ADA requirements Light pole base on east side	Weather stripping and sill caps not installed correctly	reaged reducers missing poins at feet and vertical legs  Red Lines-As-Builts for all work under FEAD/NAVFAC	railing bent	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached	Storm Pipe not cut flush with structure and parged	Hurricane Mathew-Chiller damaged by Storm-flying debris may be the cause for this	No Surface prep before applying paint to steel	Description Cracked Mortar
										Created By Re
										Responsible Party
05/19/2017	03/31/2017	03/31/2017	04/17/2017	03/31/2017	02/24/2017	01/31/2017	12/16/2016	11/22/2016	08/09/2016	<u>Due Date</u> 11/06/2015
	New		New	New	New	New	New	New	New	Status Fix Not Accepted
and the contract of the contra	Maximax Maxima	previoulsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.	corrected	Date entered is date found / damaged	date entered is date found	Date entered is date found	QCM will inpsect all manholes upon closeout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.		Date entered is date found	Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.
63	70	99	99	100 140	140 00	183	189	240	324	601

www.submittalexchange.com

Report Type: Open Items

Project:

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Days Open Calculated by: Calendar Days since date Initially Created

Date:

6/15/2017

Total Items: 23

Log:	Re-Work Log						Days Open Calculated by: Calen	Days Open Calculated by: Calendar Days since date midally created
Item#	Location	Description	Created By	Responsible Party	Due Date	Status	Comments	Days Open
115	Various locations - Communication rooms	Fire rated comm backboard not UL labeled		6	05/31/2017	New		67
116	Room 106 top of walls	Gypsum board wall supports on south wall exposed			05/31/2017	New		2 2
120	East side of hangar - Counterpoise system	Insulated cable used for counterpoise - Must not be insulated			06/02/2017	New		46 21
121	1st floor mech/water room	Block cracked from 1st floor to 2nd floor where column exists			06/23/2017	New		÷ 5
122	Behind corner guard and marker boards	Walls not painted behind comer guards and markerboards			06/23/2017	New		÷ 5
123	Various block walls throughout admin area	Cracks in block walls close to expansion joints and columns			06/23/2017	New		ń č
124	Block wall on NW side of corridor	Block wall on northwest side of corridor concave approx 1/4"			06/23/2017	New		
125	2nd floor admin through wall flashing	Trim back modified shelf angle east of the curtainwall uniformly			06/30/2017	New	Per discussion with STOA.	
126	Lobby area	Corners of block walls not rounded above approx 10'			06/30/2017	New		n o
127	General throughout building	Corners of block walls need to be finished and rounded better. Also not rounded all the way up			06/30/2017	New		. 0



Log: Section Compressors (100HP And Larger) 211313.0020 Wet-Pipe Sprinkler **Project**: Report Type 412213.15 Bridge Operation Generator Nonlubricated Systems, Fire General 019113.0025 Report E 263213.0020 Single Rotary Screw Air 221519.1920 Protection Construction Requirements For Commisioning Station G Submittal Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air All Items 263213.002 0-7 221519.192 0-3 211313.002 0-9 019113.002 5-4 item# 412213.15-4 requirements for construction commissioning plan, prefunctional Transmittal #680 Bridge crane hook and wire rope certificate, magnetic particle report Generator Sets Training Plan Transmittal #670 Single Operation Transmittal #651 Non lubricated rotary checklists, and FPTs screw air compressor startup and testing and calculations Transmittal #169.4 As-built shop drawings Transmittal #654.1 Resubmittal of Transmittal #654 General commissioning Description Cincinnati Crane Supplier or Manufacturer Premier Fire TEXCAP Walker White MEP Southeast Date from Sub 05/01/2017 05/30/2017 06/08/2017 05/31/2017 05/02/2017 Date from Carothers 06/05/2017 06/14/2017 06/07/2017 06/08/2017 06/14/2017 Cons Review by Days Open Calculated by: Calendar Days since date Initially Created Arch Return to Sub Action Date: B-1-C Cons Cons Cons Cons Cons Total Items: 5 6/15/2017 Open Days 45 4 16 15

Running

Cranes, Overhead

Electric, Under

טבייסו סויו, סכ	~			SCHEDOLE	
				NE	YULY
Activity ID	Activity Description	Responsibility	Area	18 19 20 21 22 23 24 25 26 27 28 29 30	
20020	AA STORM LINE AND ASSOCIATED STRUCTURES	DEWEESE	SITE		INSTRUC
20230	AFFF TANK	DEWEESE	SITE		OIL WAT
	FINAL GRADE ON SITE	DEWEESE	SITE		
40040	SOD	SEED	SITE		
40050	SECURITY FENCE AROUND PARKING GARAGE	BRABHAM	SITE		
	UNDERGROUND FOR SECURITY FENCE	TEXCAP	SITE		
	OVERHEAD HANGAR	TEXCAP	HANG		
	сомм	TEXCAP	SITE		
	CONTROLS STARTUP	HARRIS	ADMIN		
	SIDE WALKS	WALDROP	SITE		
27060	TRANSLUCENT WALL PANELS	CAROLINA	HANG		
	CEILING TILE SECOND FLOOR	CAROTHERS	ADMIN		
26090	EXT WINDOWS	CLEARVIEW	ADMIN		FINAL CA
27120	BRIDGE CRANE 6/15 - Servel	CINCINNATI	HANG		100
28240	MILLWORK FIRST FLOOR		ADMIN		
29240	MILLWORK SECOND FLOOR	ADMINISTRAÇÃO DE LA CONTRACTOR DE LA CON	ADMIN		
29450	ELEVATOR—final list	PANHANDLE	ADMIN		WAITING
29180	PAINT SECOND FLOOR	ED	ADMIN		
28190	PAINT FIRST FLOOR	ED	ADMIN		
	PAINT GARAGE	ED	GAR		
	OVERHEAD HANGAR	WW	HANG		
	COOLING PIT ACCU	WW	HANG		
	BGSE ACCU CONTROLS	BGSE	HANG		


				JUNE	
Activity ID	Activity Description	Responsibility	Area	MT W THF S S MT W THF S S MT W THF S S M	RI
,				12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 1 2 3	
28210	FLOORING FIRST FLOOR	REGAN	ADMIN		
29220	FLOORING SECOND FLOOR	REGAN	ADMIN		
28160	CERAMIC FIRST FLOOR	REGAN	ADMIN		



Fax: (662) 234-3292

## P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 106 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 6/22/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #106

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

June 22, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

I. Safety (b) (6)

311 Days worked with Two (2) recordable incidents.

- b) Site Safety Orientations to Date:
  - Six hundred thirty-three (633) total site safety orientations have been completed to date.
- c) Accidents to Date
  - 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.
- d) First Aids to Date
  - 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.
- e) Near Misses to Date
  - Five (5), 04/06/2017 Charles DeWeese
  - Deficiency Log updated 06/20/2017
- f) Deficiency Log
  - A total of Two Hundred Seventy-three (273) deficiencies have been logged for the project.
  - No Tolerance Project began 07/19/2016
- g) AHA/Activities Reviewed:
  - N/A
- h) AHA/Activities about to start:
  - Florida Library Designs Pilot Lockers
  - AA Storm Line/Communications tie in DeWeese & Tex Cap
  - Diamond Engineering Spray Applied Fireproofing
- i) Weekly Safety Meeting Topic

Step ladder use and storage.

Excavation safety

Site clean-up/organization

Hydration



Fax: (662) 234-3292

#### II. Quality Control (b) (6)

#### a) Re-Work Log:

See Attached

### b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G</u> Submittal" Tab:

See Attached

#### c) Upcoming Preparatory Meetings:

- Finish Carpentry Florida Library Design
- Spray applied fireproofing

#### d) Upcoming Initial Meetings:

- Solid Polymer Fabrications
- 400 Hz converter-Will be scheduled once 400Hz units are set to be installed

#### e) General Quality Control Items:

- NAVFAC- Please request that BJWSA update as-builts in QC office or provide to NAVFAC and we will incorporate them into our As-Built packages. <u>Still have not received</u> from BJWSA. Received email from <u>(b) (6)</u> regarding SCEG as-builts. Will include on drawings to contact SCEG for as-built conditions
- Still awaiting MOD 06 from STOA
- Fire alarm Kingfisher transmitter antenna location Kingfisher can transmit for mass notification system. Will need a location provided. Per specs: FMCP shall be connected to the Government Furnished Government Installed base-wide mass notification interface panel. Refer to drawings for infrastructure required. When will this be installed?
- Crane testing-Testing and training scheduled for July 7th
- O&M's How are they to be turned in? One at a time or all at once at the end of the project?
- Structural and civil engineer were on site on June 13th. Still awaiting report from site visit
- Above ceiling sprinkler inspection held yesterday. First floor had no issues and second floor will need the FPE to look at some areas where duct work is potentially blocking sprinkler head coverage
- Storm structure 11D was corrected and pictures were sent to NAVFAC. Will open up 10D
  to verify that there were no bricks used improperly. It was full of water yesterday so we
  couldn't open it to verify and take pictures.
- ECS and Terracon were on site to test for concrete sidewalks. Terracon has also checked densities and pipe bedding for AA storm line and comm line installation
- Expansion joint material-Would you like it re-uploaded to SE for color selection? Remarks sent from STOA regarding installation of material in areas where concerns were raised.

#### **SAPF Issues**

- Ongoing photo documentation of SAPF construction
- Di-electric break from comm room to mechanical room for split system

#### Area B:

None

#### Ready Room:

No issues



Fax: (662) 234-3292

#### III. RFIs (Carrie Pinder):

- a) Outstanding RFIs Government
  - RFI #126 Dielectric break from comm room through G line wall: Needs to be readdressed. Discussed in QC bi-weekly meeting with (b) (6)
  - RFI #128 6" conduit from GSE-P465 manhole. Forwarded onto (b) (6)
     TEXCAP for response
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #236 Solar storage tank and domestic hot water storage tank damaged skins
- d) Outstanding RFVs
  - None

#### IV. RFPs/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

- PC-035 Unforeseen condition. Additional material above original quote. Revision resent 6/12 to NAVFAC with verbal approval. No Contract Modification received to date.
- PC-045 Raising of existing Manhole Cover and Frame in Parking Lot. Submitted 5/25.
- **REA** Apron Infill Unsuitable Soil Condition Negotiated 6/9 and resubmitted with revised pricing 6/12. Awaiting Contract Modification from the Navy.
- **REA** Parking Garage Enlarged Pile Cap Negotiated 6/9 and resubmitted with revised pricing 6/12. Awaiting Contract Modification from the Navy.

#### In Development:

- PC-044 BJWSA Utility conflict CDCI compiling pricing. Should be submitted.
- PC-046 Epoxy flooring add RM 125. Awaiting quote from subcontractor.

#### Storm-water/Erosion Controls -

- **SWPPP** Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Drop inlet protection refurbished 6/21 after rain event
  - Silt bags being utilized on all excavation dewatering
  - Sweeping frequently in areas prone to tracking and concentrating in the tow way and flight line area

#### V. Schedule (Adam Blaylock):

See Attached Schedule

#### Administrative (Randy Hoffland)

- AA storm drain line
- Next Redzone Meeting, 11 July 2017
- O&M training
- FF&E Re-schedule for 24 July



Fax: (662) 234-3292

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.

## eport By (b) (6)

Project: Report Type: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Open Items Date: Total Items: 23 6/21/2017

127	126	125	124	123	122	121	120	116	<u>Item#</u> 115	Log:
General throughout building	Lobby area	2nd floor admin through wall flashing	Block wall on NW side of corridor	Various block walls throughout admin area	Behind comer guard and marker boards	1st floor mech/water room	East side of hangar - Counterpoise system	Room 106 top of walls	Location Various locations - Communication rooms	Re-Work Log
Corners of block walls need to be finished and rounded better. Also not rounded all the way up	Corners of block walls not rounded above approx 10'	Trim back modified shelf angle east of the curtainwall uniformly	Block wall on northwest side of corridor concave approx 1/4"	Cracks in block walls close to expansion joints and columns	Walls not painted behind corner guards and markerboards	Block cracked from 1st floor to 2nd floor where column exists	Insulated cable used for counterpoise - Must not be insulated	Gypsum board wall supports on south wall exposed	Description  Fire rated comm backboard not UL labeled	
									Created By	
									Responsible Party	
06/30/2017	06/30/2017	06/30/2017	06/23/2017	06/23/2017	06/23/2017	06/23/2017	06/02/2017	05/31/2017	Due Date 05/31/2017	
New	New	New	New	New	New	New	New	New	<u>Status</u> New	
		Per discussion with STOA, Pete and Scott							Comments	Days Open Calculated by: Calendar Days since date Initially Created
12	12	14	21	21	21	21	27	63	Days Open 63	date Initially Created



Project: Report Type: Open Items Date: 6/21/2017

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Re-Work Log Days Open Calculated by: Calendar Days since date Initially Created Total Items: 23

Log:

114	113	110	106	105	103	101	93	90	89	87	75	1tem#
East side of parking garage	Parking Lot	Various exterior windows throughout admin area	On site within project limits	Hangar- east/west end	second floor railing . South elevation	2nd floor elevator threshold	Roof Hatch Safety Railing	Room 131 Water Room	Structure 11D and 10D	Chiller Location	East Elec Room#111	<u>Location</u> BOX CULVERT
Light pole base on east side of parking garage not level	Handicap sidewalks do not meet ADA requirements	Weather stripping and sill caps not installed correctly	Red Lines-As-Builts for all work under FEAD/NAVFAC	caged ladders missing bolts at feet and vertical legs	railing bent	Fire Rated Expansion Joint Material flashing is damaged and will need to be replaced.	this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached	Storm Pipe not cut flush with structure and parged	Hurricane Mathew- Chiller damaged by Storm- flying debris may be the cause for this	No Surface prep before applying paint to steel	<u>Description</u> Cracked Mortar
												Created By
												Responsible Party
05/19/2017	04/21/2017	03/31/2017	03/31/2017	03/31/2017	04/17/2017	03/31/2017	02/24/2017	01/31/2017	12/16/2016	11/22/2016	08/09/2016	<u>Due Date</u> 11/06/2015
New	New	New	New	New	New	New	New	New	New	New	New	Status Fix Not Accepted
			previoutsy asked both NAVFAC/SCE&G/and BJWSA with no response or action taken.		adam blaylock will notify QC dept once corrected	Date entered is date found / damaged	date entered is date found	Date entered is date found	QCM will inpsect all manholes upon doseout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.		Date entered is date found	Comments  Work has been completed,QC inspections were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.
69	76	97	105	105	106	146	188	189	195	246	330	Days Open 607



### ort E(b) (b)

Report Type:	All Items									Date: 6	6/21/2017
Project:	Beaufort, SC Aircra Station	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station								Total	Total Items: 3
Log:	G Submittal					Day	Days Open Calculated by: Calendar Days since date Initially Created	ed by: Calendar	Days since	date Initially	Created
Section	Item#	Description	Supplier or Manufacturer	Date from Sub	Date from Carothers	Review by Cons	Review by Arch	Return to Sub	Action	B-I-C	Days Open
019113.0025 General Commisioning Requirements For Construction	019113.002 5-4	Transmittal #654.1 Resubmittal of Transmittal #654 General commissioning requirements for construction commissioning plan, prefunctional checklists, and FPTs	MEP Southeast	06/08/2017	06/14/2017					Cons	3
211313.0020 Wet- Pipe Sprinkler Systems, Fire Protection	211313.002 0-9	Transmittal #169.4 As-built shop drawings and calculations	Premier Fire	05/30/2017	06/08/2017					Cons	22
263213.0020 Single Operation Generator Sets	gle 263213.002 ntor 0-7	Transmittal #670 Single Operation Generator Sets Training Plan	TEXCAP	05/02/2017	06/14/2017					Cons	50

מבייסו סונו, סכ				30117011	
				NE J	LY
Activity ID	Activity Description	Responsibility	Area	MTWTHFSSMTWTHFSSMTWTHFSS	3
				19 20 21 22 23 24 25 26 27 28 29 30 1 2 3 4 5 6 7 8 9	9 10
20020	AA STORM LINE AND ASSOCIATED STRUCTURES	DEWEESE	SITE		
20230	AFFF TANK	DEWEESE	SITE		OIL WAT
	FINAL GRADE ON SITE	DEWEESE	SITE		
40040	SOD	SEED	SITE		
40050	SECURITY FENCE AROUND PARKING GARAGE	BRABHAM	SITE		
	UNDERGROUND FOR SECURITY FENCE	TEXCAP	SITE		
	OVERHEAD HANGAR	TEXCAP	HANG		
	COMM	TEXCAP	SITE		
	CONTROLS STARTUP	HARRIS	ADMIN		
	SIDE WALKS	WALDROP	SITE		
27060	TRANSLUCENT WALL PANELS	CAROLINA	HANG		
	CEILING TILE SECOND FLOOR	CAROTHERS	ADMIN		
26090	EXT WINDOWS	CLEARVIEW	ADMIN		HINAL CA
28240	MILLWORK FIRST FLOOR	CINCININATI	ADMIN		
29240	MILLWORK SECOND FLOOR		ADMIN		
29450	ELEVATOR	PANHANDLE	ADMIN		WAITING
29180	PAINT SECOND FLOOR	ED	ADMIN		
28190	PAINT FIRST FLOOR	ED	ADMIN		
	PAINT GARAGE	ED	GAR		
	OVERHEAD HANGAR	WW	HANG		
	COOLING PIT ACCU	WW	HANG		The second secon
	BGSE ACCU CONTROLS	BGSE	HANG		

				JONE	
Activity ID	Activity Description	Responsibility	Area	M T W TH F S S M T W TH F S S M T W TH F S S M	/ RE
				19 20 21 22 23 24 25 26 27 28 29 30 1 2 3 4 5 6 7 8 9 10	10
28210	FLOORING FIRST FLOOR	REGAN	ADMIN		
29220	FLOORING SECOND FLOOR	REGAN	ADMIN		
28160	CERAMIC FIRST FLOOR	REGAN	ADMIN		




P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820 Fax: (662) 234-3292

- - - - -

## P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 87 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 2/2/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #87

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

February 2, 2017-1:00 pm - 2:00pm

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

#### I. Safety (Mack Smoot III):

a) 172 Days worked with Two (2) recordable incidents.

#### b) Site Safety Orientations to Date:

• Five Hundred Fourteen (514) total site safety orientations have been completed to date.

#### c) Accidents to Date

• 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.

#### d) First Aids to Date

• 1 new First Aid has been reported since our last meeting. Total of Fifteen (16) First Aids have been recorded to date. (Admin staff cut finger)

#### e) Near Misses to Date

• Four (4) no new items (Deficiency Log updated 02/01/2017)

#### f) Deficiency Log

- A total of **Two Hundred & Six (206)** deficiencies have been logged for the project. (1 note added)
- No Tolerance Project began 07/19/2016

#### g) AHA/Activities Reviewed:

- Walker White 11 AHA's submitted various scopes
- Tex Cap 5 AHA submitted (Still have 5 more to submit awaiting documents)
- Regan Tile Awaiting certifications
- Ace Doors Awaiting certifications
- DeWeese Changes being made for re-submission

#### h) AHA/Activities about to start:

- Mastercraft Flooring Awaiting AHA approval
- DeWeese AFFF awaiting approval

#### i) Weekly Safety Meeting Topic

- PPF
- Hangar Work (Various subs at the same time)
- Injuries



Fax: (662) 234-3292

#### II. Quality Control (Tim Skuse):

#### a) Re-Work Log:

See Attached-

### b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G Submittal" Tab:</u>

See Attached

#### c) Upcoming Preparatory Meetings:

- \*\*Floor and Wall Tile- TBD- AHA outstanding
- \*\*Vertical Lift Fabric Door / ACE- TBD AHA outstanding
- Foam Fire Ext. for Aircraft / AFFF Containment- Safety Submittals outstanding
- Terrazzo Flooring
- Hot Mix Asphalt
- Interior / Exterior Lighting
- Spray Applied Fire Proofing

#### d) <u>Upcoming Initial Meetings:</u>

- Translucent Panels-TBD- issue of framing color
- Interior Fire Alarm and Mass Notification- routing has been checked, will schedule once initial test are completed and before devices are installed. TBD- Test Plan being revised.

#### e) General Quality Control Items:

- NAVFAC- please ask ATSI / MCAS, whoever their contract is with to request that BJWSA and SCE&G to update as-builts in my office or provide to NAVFAC, and we will incorporate them into our AS-Built packages. Will also need chlorination reports from BJWSA. Email was sent last week to both parties with no response.
- Terracon checking stability / density of backfill of parking lot lighting, sidewalks.
- ECS on site to inspect rebar, sample mortar / grout, and observe placement CMU. As well, will inspect precast- storm drainage boxes. (bases).
- Re-inspection of parking garage with Tindall was held 1/27/17 will send completed punchlist once notified of correction made.
- Deweese –scheduled remaining hydrostatic test for fire main 2/14/17, sent outlook invite to all interested parties NAVFAC please invite who you wish, Carothers FPE will be on site.
- Chiller Manuf. Tech Rep on site to repair hurricane damage. Letter will be sent once complete, and will be added to the correspondence tab of Submittal Exchange. Repairs Complete, but WW repairs are outstanding.
- Remaining switch gear breaker to be installed per ABM (testing agency) Ground and electest to be completed 2/13/17.



Fax: (662) 234-3292

#### **SAPF Issues**

- Ongoing photo documentation of SAPF construction.
- PC-38 delaying progress in this area. Need official response from NAVFAC / RFP.
- Insulation on G line- DOR on site for visual and discussion, as well as a number of other items. Field Report to be issued by STOA- <u>outstanding</u>. Ongoing QCM inspection and photo documentation in progress.
- WALKER-WHITE- Overhead inspection completed FRIDAY 1/27/17 by QCM. Electrical outstanding.
- Field Report from Mechanical DOR:
  - 1. Di-electric breaks in ready room and SAPF for hydronic piping we installed in accordance with the detail and design teams experience with other SAPF type installations.
  - 2. Di-electric break at vent through roof occurs at no-hub band coupling just below the roof line. This should be acceptable.
  - 3. Mechanical contractor to insure insulation does not cover duct access/inspection doors at any ductwork entrance into secure areas.
  - S. Curt Williams, P.E

#### Area B:

• Drywall boxes under electrical floor boxes not built yet.

#### Ready Room:

- CVCP has correct fire stopping product applied on North and East wall.-
- LM had concerns about inspection port for grills; this has been completed as of last week. Will most likely walk with them when on site Friday.

#### III. RFIs (Carrie Pinder):

- a) Outstanding RFIs Government
  - RFI #118 Fence grounding
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #226 AA storm line conflicts
  - RFI #227 Compress air disconnects
- d) Outstanding RFVs
  - None



Fax: (662) 234-3292

#### IV. . RFP's/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

- PC-037- 400 Hz Changes- Awaiting official modification
- PC-038 SAPF Security Changes—Awaiting official modification

#### In Development:

• PC-042- Triple Coat Epoxy Flooring for shop rooms in Admin. Proposal distributed to floor coating subcontractor. Awaiting quote.

#### Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Sweeping at regular intervals to eliminate tracking onto adjacent roads and taxiway
  - Sediment bags in drop inlets surrounding admin. emptied

#### V. Schedule (Adam Blaylock):

See Attached Schedule

#### Administrative (Randy Hoffland)

- Status of SCE&G contract Gas Meter
   Final tie-in to the building
- BJWSA Tie-in Water, sewer
- Red Zone Meeting February 7, 2017
- AA storm drain line
- Weekend work request
- Security Fence



Fax: (662) 234-3292

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Report Type: Open Items

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Re-Work Log

Log:

Project:

Days Open Calculated by: Calendar Days since date Initially Created

Date: 2/1/2017 Total Items: 14

ndns:www		93		90			89		88				87			82			76		75		73		70		39				35	Item#
www.submittalexchange.com	Ç	Roof Hatch Safety Railing	Room	Room 131 Water			Structure 110	above ACCU trench	West Wall Veneer				Chiller Location		Cable Tray	First Floor Corridor		128 Airframes Office	South wall of room		East Elec Room#111	P7	Parking Garage line	Veneer	West Ext Precast /	Beams	Pile Caps & Grade				BOX CULVERI	
	roof color.	this color is safety yellow and on IEC plans, it is to match the	attached	Tanks damaged see photos	ç	structure and parged	of masons	will be corrected upon return	Brick damaged and cracked	this	debris may be the cause for	damaged by Storm- flying	Hurricane Mathew- Chiller	cable tray	need to be removed from	Overspray from painters will	hangar.	is in CMU inculding joint and	Plumbing pipe at top of the wall	applying paint to steel	No Surface prep before	first level East Flevation	Cracks in bottome level and	Veneer	Paint on Exterior Precast and	Col. Line 10/A	Broken & Bent Anchor Bolts -				Cracked Mortar	Description
																												\ \				Created By
																							θ					\				Responsible Party
		02/24/2017		01/31/2017		01.07/01/71	10/40/00/10		12/24/2016				11/22/2016			09/16/2016			09/02/2016		08/09/2016		08/05/2016		06/30/2016		11/30/2015				11/06/2015	Due Date
		New		New		New			New				New			New			Reviewed by GC		New		New		New		New				Fix Not Accepted	Status
		date entered is date found		NAVFAC.  Date entered is date found	progress. Date entered is date found by	and completion of this FOW FOW is work in			date entered is date found							date entered is date found		installation	Pipe is removed, please correct CMU	To the second se	Date entered is date found		Date entered is Date Found		Date Entered is Date Found		In process of being repaired now.	questioning entire installationno change in	of correction, NAVFAC QA is now	were held and deficient areas were remediated, pictures were provided as proof	Work has been completed,QC inspections	Comments
0000 4 050		48		49		S	1		97				106			148			167		190		202		222		450				467	Days Open

Project: Report Type: Re-Work Log Open Items Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Days Open Calculated by: Calendar Days since date Initially Created Date: 2/1/2017 Total Items: 14

	101		100	llem#	-
threshold	Elevation of Admin 2nd floor elevator	Tower North / East Window on South	Parking garage Stair	Location	
Material flashing is damaged and will need to be replaced.	Fire Rated Expansion Joint	specification	Failed required field test per	Description	
				Cardada B. W. Walton IV	
	02/17/2017		01/25/2017	Due Date	
	New		New	Status	
	Date entered is date found / damaged	scheduled.	Will polify Navigo of Refeet oppo	Comments	may be a four a succession of a succession and a succession of the succession of
	<b>5</b>	!	21	Days Open	

Design-Build

Carothers Construction, Inc.



CONSTRUCTION INC.

Report Type:

G Submittal

Log: Project:

Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station

Date: 2/1/2017

Days Open Calculated by: Calendar Days since date Initially Created Total Items: 27

013526.0525 Government Safety Requirements for	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	Section
013526.0525- 257	013526.0525- 255	013526.0525- 254	013526.0525- 253	013526.0525- 252	013526.0525- 251	013526.0525- 250	013526.0525- 249	Item#
Submittal #601 AHA for Regan Tile for Ceramic Tile 01-26-2017	Submittal #599 AHA for CCI for Acoustical Ceilings 01/25/2017	Submittal #598 AHA for CCI for Metal Stud Framing 01/25/2017	Submitall #597 AHA for CCI for Gypsum Board/Sheetrock 01/25/2017	Submittal #596 CCI for Fire Caulking/Protection 01/25/2017	Submittal #595 AHA for CCI for Insulation 01-25-2017	Submittal #594 AHA for Shoring/DeWatering for AFFF Charles DeWeese 01-25-2017	Submittal #593 AHA for Flexible Lifelines for Fall Protection Instillation 01-24-2017	Description
Regan Tile	Carother Construction Inc.	Carother Construction Inc.	Carother Construction Inc.	Carother Construction Inc.	Carother Construction Inc.	Charles DeWeese	Flexible Lifeline Systems	Supplier or Manufacturer
01/26/2017	01/25/2017	01/25/2017	01/25/2017	01/25/2017	01/25/2017	01/24/2017	01/23/2017	Date from Sub
01/26/2017	01/25/2017	01/25/2017	01/25/2017	01/25/2017	01/25/2017	01/25/2017	01/24/2017	Date from Carothers
								Review by
								Review by Arch
								Return to
								Action
Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	B-I-C
6	7	7	7	7	7	œ	9	<u>Days</u> <u>Open</u>

Report Type:	All Items	од до населения учение учение поставления пределения пределения поставления в пределения учение в поставления								Date:	Date: 2/1/2017
Project:	Beaufort, SC Air	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	tation							Total !	Total Items: 27
Log:	G Submittal					Day	Days Open Calculated by: Calendar Days since date Initially Created	ted by: Calenda	r Days since	date Initially	Created
Section	Item#	Description	Supplier or Manufacturer	Date from Sub	Date from Carothers	Review by	Review by	Return to	Action	B-I-C	<u>Days</u> <u>Open</u>
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 258	Submittal #602 AHA for Tex Cap for Interior Lighting 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	6
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 261	Submittal #604 AHA for Tex Cap for Exterior Lighting 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	6
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 262	Submittal #605 Tex Cap for 400hz Converter 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	60
013526,0525 Government Safety Requirements for Design-Build	013526.0525- 263	Submittal #606 Tex Cap for ATS Installation 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	6
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 264	Submittal #607 Tex Cap for Variable Frequency Drive 01/27/2017	Tex-Cap	01/27/2017	01/27/2017					Cons	И
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 265	Submittal #608 Walker White for Nonlubricated Rotary Screw Air Compressor 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	_
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 266	Submittal #609 Walker White for Water Chillers 01-31-2017	Walker White	01/31/2017	01/31/2017		,			Cons	_
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 267	Submittal #610 Walker White for Facility Gas Piping 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	_
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 268	Submittal #611 Walker White for Common HVAC Piping 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	_

Report Type:	All Items	Date: 2/1/2017
Project:	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	Total Items: 27
Log:	G Submittal	Days Open Calculated by: Calendar Days since date Initially Created

263543 400-Hertz (Hz) Solid State Frequency Converter / 270VDC Ground Power Systems	095100 Acoustical Ceilings	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	Design-Build 013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	Section 013526.0525 Government Safety Requirements for
263543-3	095100-5	013526.0525- 275	013526.0525- 274	013526.0525- 273	013526.0525- 272	013526.0525- 271	013526.0525- 270	Item# 013526.0525- 269
Aircraft power cable assembly & Frequency converter & Frequency converter converter converter & Frequency converter drawings & Performance Tests & Preliminary Operation and Maintenance Manuals & Qualifications of manufacturer & Remote Monitoring and C	Transmittal #614 Acoustical ceiling tite sample	Submittal #620 Walker White for Electric Unit Heaters 02-01-2017	Submittal #619 Walker White for Heating System 02-01-2017	Submittal #618 Walker White for Air COnditioning Equipment 02-01-2017	Submittal #617 Walker White for Chemical Treatment Piping 02-01-2017	Submittal #616 Walker White for Low Temperature Water Heating Systems 02-01-2017	Submittal #615 Walker White for Sump Pumps 02-01-2017	Description Submittal #612 Walker White for Solar Heating Water Piping 01-31-2017
BGSE	Carothers Construction	Walker White	Walker White	Walker White	Walker White	Walker White	Walker White	Supplier or Manufacturer Walker White
11;09;2016	01/30/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	<u>Date from</u> <u>Sub</u> 01/31/2017
12/17/2016	01/30/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	Date from Carothers 01/31/2017
								Review by Cons
								Review by Arch
								Return to Sub
								Action
Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons
84	2	_	_	<u> </u>	<u>.</u>	_		<u>Days</u> <u>Open</u>

Power Systems	Converter / 270VDC Ground	Frequency	263543 400-Hertz	Section	Log:	Project:
			263543-5	Item#	G Submittal	Beaufort, SC Ai
		power cable stand	Transmittal #455.2 400 Hz Solid State	Description		Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station
			BGSE	Supplier or Manufacturer		Station
			12/19/2016	Date from Sub		
			01/17/2017	Date from Carothers		
				Review by Cons	Day	
				Review by Arch	Days Open Calculated by: Calendar Days since date Initially Created	
				Return to Sub	ed by: Calendar	
				Action	Days since	
			Cons	B-I-C	date Initiali	Total
			44	<u>Open</u>	y Created	Total Items: 27

Report Type:

All Items

Date: 2/1/2017

P465 HANGAR BEAUFORT, SC

																				GAR	0	EBCI	HANDRAILS	35050
WAITING										$\dashv$	-	-								HANG		CAROLINA	TRANSLUCENT WALL PANELS	27060
		10/10												1						SITE		WALDROP	SIDE WALKS	
COMPLE																				SITE		WALDROP	ROADWAY CONCRETE AROUND HANGAR	
																				SITE		WALDROP	DUMPSTER PAD CONCRETE	30220
																				HANG		PREMIER	FOAM SUPPRESSION SYSTEM TRENCHES	
							12.11													HANG		PREMIER	OVERHEAD SPRINKLER HANGAR	
EXTERIO																				HANG	Ŧ	TEXCAP	ELECTRICAL FOR COOLING PITS	
																				HANG	Ŧ	TEXCAP	OVERHEAD HANGAR	THE PROPERTY OF THE PROPERTY O
SAPF								* * *												ADMIN	AC	TEXCAP	ABOVE CEILING ELEC ROUGH IN 2 FL ADMIN	29030
OVERHE/																				ADMIN	AD	TEXCAP	ABOVE CEILING ELEC ROUGH IN 1 FL ADMIN	28040
																				SITE	S	TEXCAP	UNDERGROUND FOR SECURITY FENCE	
ROUGHIN																				SITE	S	TEXCAP	NEW LIGHT POLE STANDARDS	30210
GAS LINE																				SITE	S	SCEG	SCEG NEW GAS SERVICE	20260
MAKE CC																Ţ				SITE	۲۵.	BJWSA	BJWSA DW LOOP AROUND HANGAR	20330
																1				SITE		WALDROP	AA STORM LINE PRECAST DRAINAGE STRUCTURES	
COMPLET																				SITE		DEWEESE	GRADE AND BASE FOR ROAD AROUND HANGAR	
																				SITE		DEWEESE	FINAL GRADE ON SITE	
RFI SUBN																				SITE		DEWEESE	AA STORM LINE AND ASSOCIATED STRUCTURES	20020
							10000																	
	9	$\infty$	7	16	15	14		-		9 10		7	<b>.</b>	5	4	-	2	<u></u>	_	Aled IV		nesponsibility	received prescription	
D.	,, ⋜	0	Ω	TH F	FEBRUARY	一品	3	0	0	d n		¬ {	<b>≤</b>	^	Λ	Π	럳		JANUARY M T W			Responsibility	Activity Description	Activity ID


				JANUARY FEBRUARY	
Activity ID	Activity Description	Responsibility	Area	M T W TH F S S M T W TH F S S M T W TH F S S M	RE
				30 31 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	
35030	ALUMINUM STOREFRONTS	CLEARVIEW	GAR		
26090	EXT WINDOWS	CLEARVIEW	ADMIN		
29140	TAPE AND FINISH DRYWALL 2ND FLOOR	CCI	ADMIN		WAITING
	CEILING GRID 2ND FLOOR	CCI	ADMIN		WAITING
	INSULATE WALLS 1ST FLOOR	CCI	ADMIN		
	HANG DRYWALL 1ST FLOOR	CCI	ADMIN		WAITING
	ELEVATOR	PANHANDLE	ADMIN		WAITING
	MISC STEEL FOR MEGA DOOR	EBCI			
	MEGA DOOR	ACE	HANG		
28080	ABOVE CEILING PLBG PIPE 1 FL ADMIN	WW	ADMIN		
28100	ABOVE CEILING MECH PIPE 1 FL ADMIN	WW	ADMIN		
29050	ABOVE CEILING PLBG PIPE 2 FL ADMIN	WW	ADMIN		WAITING
29080	ABOVE CEILING MECH PIPE 2 FL ADMIN	WW	ADMIN		WAITING
	LOUVERS HANGAR	WW	HANG		
28030	HANG DUCTWORK FIRST FLOOR	WW	ADMIN		
	DUCTWORK FOR COOLING PITS	WW	HANG		EXTERIO
	STORM DRAIN PPING IN GARAGE	WW	GAR		
	OVERHEAD HANGAR	WW	HANG		
	CERAMIC SECOND FLOOR	REGAN	ADMIN		
26080	2" RIGID INSULATION ADMIN	BUTLER	ADMIN		



Fax: (662) 234-3292

## P- 465 AIRCRAFT HANGAR OWNERS WEEKLY PROGRESS MEETING # 88 CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 2/9/2017





Fax: (662) 234-3292

#### Carothers/NAVFAC Weekly Meeting #88

Project:

P465 Aircraft Hangar

Contract:

N69450-14-D-1266

Date:

February  $\overline{9,2017-1:00 \text{ pm}} - 2:00 \text{pm}$ 

Location:

Carothers Jobsite Trailer 450T Corrosion Loop

#### Agenda:

#### I. Safety (Mack Smoot III):

a) 180 Days worked with Two (2) recordable incidents.

#### b) Site Safety Orientations to Date:

• Five Hundred Fourteen (514) total site safety orientations have been completed to date.

#### c) Accidents to Date

• 0 new Accident has occurred since our last meeting. Two (2) lost time Accidents have been recorded to date.

#### d) First Aids to Date

• 0 new First Aid has been reported since our last meeting. Total of Sixteen (16) First Aids have been recorded to date.

#### e) Near Misses to Date

- Four (4), no new items
- Deficiency Log updated 02/08/2017

#### f) Deficiency Log

- A total of Two Hundred Ten (210) deficiencies have been logged for the project.
- No Tolerance Project began 07/19/2016

#### g) AHA/Activities Reviewed:

- Walker White Louvers Installation submitted
- Tex Cap Waiting for competent Person Letter
- Regan Tile Re-submitted
- Ace Doors Re-Submitted
- DeWeese Crane plan re-submitted/de-watering/shoring

#### h) AHA/Activities about to start:

• Deco – Demo of steam vault

#### i) Weekly Safety Meeting Topic

- PPE
- Clean up
- Documentation (Certifications)
- Smoking Area



Fax: (662) 234-3292

#### II. Quality Control (Tim Skuse):

#### a) Re-Work Log:

See Attached-

### b) <u>Submittal Under Review by NAVFAC or Action within Submittal Exchange "G Submittal" Tab:</u>

See Attached

#### c) Upcoming Preparatory Meetings:

Too many unapproved AHA's to track what is up coming.

#### d) <u>Upcoming Initial Meetings:</u>

- Translucent Panels-TBD- issue of framing color
- Interior Fire Alarm and Mass Notification- routing has been checked, will schedule once initial test are completed and before devices are installed. TBD- Test Plan being revised.
- Foam Fire Ext. For Aircraft 2/14/17

#### e) General Quality Control Items:

- NAVFAC- please ask ATSI / MCAS, whoever their contract is with to request that BJWSA and SCE&G to update as-builts in my office or provide to NAVFAC, and we will incorporate them into our AS-Built packages. Will also need chlorination reports from BJWSA. Outstanding
  - BJWSA Responded regarding As-Builts, but SCEG has not.
- Terracon checking stability / density of backfill of parking lot lighting, sidewalks.
- ECS on site to inspect rebar, sample mortar / grout, and observe placement CMU. As well, placing 5000 PSI diamonds for Hangar SOG around columns. Also on site for weld inspection of LTW tube steel supports.
- Deweese –scheduled remaining hydrostatic test for fire main 2/14/17, sent outlook invite to all interested parties NAVFAC please invite who you wish, Carothers FPE will be on site.
- Remaining switch gear breaker to be installed per ABM (testing agency) Ground and electest to be completed 2/13/17.
- Window re-tests failed yesterday, but retesting today. No notice given to NAVFAC due to sub not scheduling correctly. I appreciate your time, due to short notice.
- Once again, all curb and gutter deficient work will be replaced before asphalt. The QC dept and Super are well aware of areas that need removal. If NAVFAC would like to mark areas they are concerned about please use chalk / or water based marking paint. Do not use a color that is used for utilities!



Fax: (662) 234-3292

#### **SAPF Issues**

Ongoing photo documentation of SAPF construction.

Insulation on G line- DOR on site for visual and discussion, as well as a number of other items. – Field Report to be issued by STOA- <u>outstanding</u>. Ongoing QCM inspection and photo documentation in progress. <a href="Photos being placed on CD for LM">Photos being placed on CD for LM</a>.

Previously missed during inspection was security bars and inspection port for louver exiting SAPF east wall in room 236 ALIS Storage.

#### Area B:

• Drywall boxes under electrical floor boxes not built yet.

#### Ready Room:

• No Issues other than level finish above ceiling.

#### III. RFIs (Carrie Pinder):

- a) Outstanding RFIs Government
  - RFI #118 Fence grounding
  - RFI #119 Compress air disconnects Answered by email
- b) Outstanding RFIs SAPF
  - None
- c) Outstanding RFIs STOA
  - RFI #226 AA storm line conflicts
- d) Outstanding RFVs
  - None

#### IV... RFP's/Change Orders:

(Please reference Owners Modification Log)

#### **Submitted Awaiting Approval:**

- PC-037- 400 Hz Changes- Awaiting official modification
- PC-038 SAPF Security Changes—Awaiting official modification

#### In Development:

• PC-042- Triple Coat Epoxy Flooring for shop rooms in Admin. Proposal distributed to floor coating subcontractor. Awaiting quote.

#### Storm-water/Erosion Controls-

- SWPPP Storm water and Sediment controls have been installed and maintained according to the onsite SWPPP plan
  - Sweeping at regular intervals to eliminate tracking onto adjacent roads and taxiway
  - Sediment bags in drop inlets surrounding admin. emptied



Fax: (662) 234-3292

#### V. Schedule (Adam Blaylock):

See Attached Schedule

#### Administrative (Randy Hoffland)

- Status of SCE&G contract Gas Meter
   Final tie-in to the building
- BJWSA Tie-in Water, sewer
- Red Zone Meeting March 7, 2017
- AA storm drain line
- Weekend work request

#### Notice:

Any discrepancies regarding this coordination meeting should be directed to Carothers within 48 hours. Any corrections will be addressed in an addendum to the meeting minutes. After 48 hours, the minutes will be considered binding and any corrections and actions shown will be expected.



Total Items: 14

Project: Report Type: Open Items Re-Work Log Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station Days Open Calculated by: Calendar Days since date Initially Created Date: 2/9/2017

93	90	89	88	87	82	76	75	70	39	11 Hem #
Roof Hatch Safety Railing	Room 131 Water Room	Structure 11D	West Wall Veneer above ACCU trench hetween col C/D	Chiller Location	First Floor Corridor Cable Tray	South wall of room 128 Airframes Office	Parking Garage line P7 East Elec Room#111	Beams West Ext Precast / Veneer	Pile Caps & Grade	# Location BOX CULVERT
this color is safety yellow and on IFC plans, it is to match the roof color.	Tanks damaged see photos attached	Storm Pipe not cut tlush with structure and parged	this  Brick damaged and cracked will be corrected upon return of masons	cable tray Hurricane Mathew- Chiller damaged by Storm- flying debris may be the cause for	hangar.  Overspray from painters will need to be removed from	applying paint to steel Plumbing pipe at top of the wall is in CMU incutding joint and	Cracks in bottome level and first level East Elevation No Surface prep before	Col. Line 10/A Paint on Exterior Precast and Veneer	Broken & Bent Anchor Bolts -	Description Cracked Mortar
timothy skuse	timothy skuse	timothy skuse	timothy skuse	timothy skuse	timothy skuse	timothy skuse	timothy skuse timothy skuse	timothy skuse	Chuck Rose	Created By timothy skuse
Raymond Lewis	Jeff Pratt	Chase Thomason	CS	Jeff Pratt	Mike Shepard	CS S	Jonathan Cochrane Mike Shepard	strialconcrete net Mike Shepard	mhernandez@indu	Responsible Party timothy skuse
02/24/2017	01/31/2017	12/16/2016	12/24/2016	11/22/2016	09/16/2016	09/02/2016	08/05/2016 08/09/2016	06/30/2016	11/30/2015	Due Date 11/06/2015
New	New	New	New	New	New	Reviewed by GC	New New	New	New	Status Fix Not Accepted
date entered is date found	Date entered is date found	QCM will inpsect all manholes upon closeout and completion of this FOW. FOW is work in progress. Date entered is date found by NAVFAC.	date entered is date found		date entered is date found	Pipe is removed, please correct CMU installation	Date entered is Date Found  Date entered is date found	Date Entered Is Date Found	were held and deficient areas were remediated, pictures were provided as proof of correction, NAVFAC QA is now questioning entire installationno change in this issue for several months.  In process of being repaired now.	Comments Work has been completed,QC inspections
56	57	និ	105	114	156	175	210 198	230	458	Days Open 475

Item#	Location	Description	Created By	Responsible Party	Due Date	Status	Comments	Days Open
100	Parking garage Stair Tower North / East	Failed required field test per specification	timothy skuse	Cary Lewis	01/25/2017	New	Will notify Navfac of Retest, once scheduled.	29
101	Window on South Elevation of Admin 2nd floor elevator threshold	Fire Rated Expansion Joint Material flashing is damaged	timothy skuse	Joe Winstead	02/17/2017	New	Date entered is date found / damaged	
		and will need to be replaced.						



and fembricated and a second contact and a second	PERMITTER PERMITTER CONTRACTOR CO						Our Bus	Our Business is Bushberg Siese 1987	****		
Report Type:	All Items					жина свида одвержира ведавшинений извений извений из	та инивередна сущейнами вазилунарный изграфияния			Date: 2	Date: 2/9/2017
Project:	Beaufort, SC Ai	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	Station							Total the	Total Items: 26
Log:	G Submittal					Day	Days Open Calculated by: Calendar Days since date Initially Created	ted by: Calendar	r Days since o	date Initially (	Created
		винациойний изиванции изивання проделення пределення в пределення в предоставления в предос		вінен верей	на ответительности на перетигна подраждения в предоставления в предоставле	AND COLOR OF THE PROPERTY AND A PROPERTY OF THE PROPERTY OF TH	ACEU ANTONIOSIONI CAMPAN PROPERTO DE PROPE	enterente de la compara destada e elimenta de destada estada enterente enterente enterente enterente enterente		Page 1 Special	
Section	Item#	Description	Supplier or Manufacturer	Date from Sub	Date from Carothers	Review by	Review by Arch	Return to Sub	Action	B-1-C	<u>Days</u> Open
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 258	Submittal #602 AHA for Tex Cap for Interior Lighting 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	14
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 261	Submittal #604 AHA for Tex Cap for Exterior Lighting 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	14
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 262	Submittal #605 Tex Cap for 400hz Converter 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	4
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 263	Submittal #606 Tex Cap for ATS Installation 01-26-2017	Tex-Cap	01/26/2017	01/26/2017					Cons	14
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 264	Submittal #607 Tex Cap for Variable Frequency Drive 01/27/2017	Tex-Cap	01/27/2017	01/27/2017					Cons	3
013526.0525 Government Safety Requirements for Design-Build	013526 0525- 265	Submittal #608 Walker White for Nonlubricated Rotary Screw Air Compressor 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	9
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 266	Submittal #609 Walker White for Water Chillers 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	9
013526.0525 Government Safety Requirements for Design-Build	013526.0525- 267	Submittal #610 Walker White for Facility Gas Piping 01-31-2017	Walker White	01/31/2017	01/31/2017					Cons	9

Report Type:	All Items									Date: 2/9/2017	)/2017
Project:	Beaufort, SC Air	Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station	ation							Total Items: 26	าร: 26
Log:	G Submittal					Day	s Open Calculat	Days Open Calculated by: Calendar Days since date Initially Created	Days since (	date Initially Co	reated
8			Supplier or	Date from	Date from	Review by	Review by	Return to			Days
Section	Item#	Description	Manufacturer	Sub	Carothers	Cons	Arch	Sub	Action	B-1-C	Open
013526.0525	013526.0525-	Submittal #611 Walker White for Common	Walker White	01/31/2017	01/31/2017					Cons	9
Government Safety Requirements for	268	HVAC Piping 01-31-2017									
Design-Build											
013526.0525	013526.0525-	Submittal #612 Walker White for Solar	Walker White	01/31/2017	01/31/2017					Cons	9
Government Safety	269	Heating Water Piping 01-31-2017									
Requirements for											
Design-Build											
013526.0525	013526.0525-	Submittal #615 Walker White for Sump	Walker White	01/31/2017	02/01/2017					Cons	9
Concernment Sefet.	070	D									

013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526 0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	Section
013526.0525- 276	013526.0525- 275	013526.0525- 274	013526.0525- 273	013526.0525- 272	013526.0525- 271	013526.0525- 270	013526.0525- 269	013526.0525- 268	Item#
Submittal #622 EMR/DART for Ace Doors 02-02-2017	Submittal #620 Walker White for Electric Unit Heaters 02-01-2017	Submittal #619 Walker White for Heating System 02-01-2017	Submittal #618 Walker White for Air COnditioning Equipment 02-01-2017	Submittal #617 Walker White for Chemical Treatment Piping 02-01-2017	Submittal #616 Walker White for Low Temperature Water Heating Systems 02-01-2017	Submittal #615 Walker White for Sump Pumps 02-01-2017	Submittal #612 Walker White for Solar Heating Water Piping 01-31-2017	Submittal #611 Walker White for Common HVAC Piping 01-31-2017	Description
Ace Doors, LLC	Walker White	Walker White	Walker White	Walker White	Walker White	. Walker White	Walker White	Walker White	Supplier or Manufacturer
02/01/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	01/31/2017	Date from Sub
02/02/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	02/01/2017	01/31/2017	01/31/2017	Date from Carothers
									Review by Cons
									Review by Arch
									Return to Sub
									Action
Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	B-1-C
σ.	9	9	9	9	9	9	9	9	Days Open

Days Open Calculated by: Calendar Days since date Initially Created	G Submittal
Total Items: 26	Project: Beaufort, SC Aircraft Maintenance Hanger at Marine Corps Air Station
Date: 2/9/2017	Report Type: All Items

270VDC Ground Power Systems	263543 400-Hertz (Hz) Solid State Frequency	263543 400-Hertz (Hz) Solid State Frequency Converter / 270VDC Ground Power Systems	095100 Acoustical Ceilings	086045 Transfucent Panels	081400 Wood Doors	013526.0525 Government Safety Requirements for Destign-Build	013526.0525 Government Safety Requirements for Destign-Build	013526.0525 Government Safety Requirements for Design-Build	013526.0525 Government Safety Requirements for Design-Build	Section
	263543-5	263543-3	095100-5	086045-12	081400-2	013526.0525- 281	013526.0525- 280	013526.0525- 279	013526.0525- 278	Item#
	Transmittal #455.2 400 Hz Solid State Frequency Converter270 VDC ground power cable stand	Aircraft power cable assembly & Frequency converter & Frequency converter converter a Grayuency converter a Grayungs & Performance Test Plan & Performance Tests & Preliminary Operation and Maintenance Manuals & Qualifications of manufacturer & Remote Monitoring and C	Transmittal #614 Acoustical celling tile sample	Transmittal #627 Transclucent panel trim color sample	Door finish colors & Transmittal #591 Wood door color samples	Submittal #628 AHA for Walker White For Louver Installation 02-08-2017	Resubmittal #603.1 AHA Charles DeWeese Crane Plan for AFFF 02-08-2017Resubmittal of Submittal #603 Crane Plan for DeWeese 01-26-2017	Resubmitall #601.1 for Regan Tile for Ceramic Tile 02-07-2017 Resubmittal of Submittal #601 AHA for Regan Tile for Ceramic Tile 01-26-2017	Resubmittal #623.1 ACE Doors for Mega Door Installation 02-06-2017Resubmittal of Submittal #623 AHA Ace Doors for Vertical Lift Fabric Doors 02-02-2017	Description
	BGSE	BGSE	Carothers Construction	Carolina Architecture	Cook and Boardman	Walker White	Charles DeWeese	Regan Tile	Ace Doors, LLC	Supplier or Manufacturer
	12/19/2016	11/09/2016	01/30/2017	02/06/2017	01/18/2017	02/08/2017	02/08/2017	02/07/2017	02/06/2017	Date from Sub
	01/17/2017	12/17/2016	01/30/2017	02/06/2017	02/08/2017	02/08/2017	02/08/2017	02/07/2017	02/06/2017	Date from Carothers
										Review by
										Review by Arch
										Return to Sub
										Action
	Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	Cons	B-1-C
	52	92	10	ω	22	_	_	N	ω	<u>Days</u> <u>Open</u>

P465 HANGAR BEAUFORT, SC

				CCBDIIADV	
Activity ID	Activity Description	Responsibility	Area	MTWTHFSSMTWTHFSSMTWTHFSSM	RE
				6	
20020	AA STORM LINE AND ASSOCIATED STRUCTURES	DEWEESE	SITE	R	RFI SUBM
AND THE PROPERTY OF THE PROPER	FINAL GRADE ON SITE	DEWEESE	SITE		
	GRADE AND BASE FOR ROAD AROUND HANGAR	DEWEESE	SITE	C	COMPLET
	AA STORM LINE PRECAST DRAINAGE STRUCTURES	WALDROP	SITE		
20330	BJWSA DW LOOP AROUND HANGAR	BJWSA	SITE		MAKE CO
20260	SCEG NEW GAS SERVICE	SCEG	SITE	S	SET METE
30210	NEW LIGHT POLE STANDARDS	TEXCAP	SITE	R	ROUGHIN
	UNDERGROUND FOR SECURITY FENCE	TEXCAP	SITE		
28040	ABOVE CEILING ELEC ROUGH IN 1 FL ADMIN	TEXCAP	ADMIN		
29030	ABOVE CEILING ELEC ROUGH IN 2 FL ADMIN	TEXCAP	ADMIN		SAPF
	OVERHEAD HANGAR	TEXCAP	HANG		
	ELECTRICAL FOR COOLING PITS	TEXCAP	HANG		EXTERIOF
	OVERHEAD SPRINKLER HANGAR	PREMIER	HANG		
	FOAM SUPPRESSION SYSTEM TRENCHES	PREMIER	HANG		
30220	DUMPSTER PAD CONCRETE	WALDROP	SITE		
	ROADWAY CONCRETE AROUND HANGAR	WALDROP	SITE		COMPLE:
	SIDE WALKS	WALDROP	SITE		
27060	TRANSLUCENT WALL PANELS	CAROLINA	HANG		WAITING
35050	HANDRAILS	EBCI	GAR		

				FEBRUARY	
Activity ID	Activity Description	Responsibility	Area	M T W TH F S S M T W TH F S S M T W TH F S S M	RE
				6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	
35030	ALUMINUM STOREFRONTS	CLEARVIEW	GAR		these concesses and affigure burns parameter services
26090	EXT WINDOWS	CLEARVIEW	ADMIN		
29140	TAPE AND FINISH DRYWALL 2ND FLOOR	CCI	ADMIN		WAITING
	CEILING GRID 2ND FLOOR	CCI	ADMIN		WAITING
	HANG DRYWALL 1ST FLOOR	CCI	ADMIN	WA	WAITING
	ELEVATOR	PANHANDLE	ADMIN	WA	WAITING
	MISC STEEL FOR MEGA DOOR	EBCI			
	MEGA DOOR	ACE	HANG		HELD UP
28080	ABOVE CEILING PLBG PIPE 1 FL ADMIN	WW	ADMIN		
28100	ABOVE CEILING MECH PIPE 1 FL ADMIN	WW	ADMIN		***
29050	ABOVE CEILING PLBG PIPE 2 FL ADMIN	WW	ADMIN	WA	WAITING
29080	ABOVE CEILING MECH PIPE 2 FL ADMIN	WW	ADMIN	WA	WAITING
	LOUVERS HANGAR	WW	HANG		
28030	HANG DUCTWORK FIRST FLOOR	WW	ADMIN		
	DUCTWORK FOR COOLING PITS	WW	HANG		EXTERIOF
	STORM DRAIN PPING IN GARAGE	WW	GAR		
	OVERHEAD HANGAR	WW	HANG		GAS PIPI
	CERAMIC SECOND FLOOR	REGAN	ADMIN		
26080	2" RIGID INSULATION ADMIN	BUTLER	ADMIN		